



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7623X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER	TO REPAIR SEE LABOUR	418.30	-
1	FRONT BUMPER BRACKET RH	NOT NECESSARY	35.00	-
1	FRONT DAY LIGHT RH	SERVICEABLE	642.50	-
1	FRONT SIDE GRILLE RH	SERVICEABLE	186.90	-
1	FRONT WHEEL CAP RH	SCRATCHED	189.50	189.50
1	RH WING MIRROR	SERVICEABLE	1,391.70	-
1	FENDER EMBLEM BLUE-DRIVE	SERVICEABLE	26.60	-
	LESS 20% DISCOUNT		-578.10	-37.90
			2,312.40	151.60
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER COVER.		700.00	350.00
	SPRAY PAINT.		600.00	250.00
	RESET WHEEL ALIGNMENT.	NOT NECESSARY	90.00	-
	CHECK LIGHTING.	NOT NECESSARY	60.00	-
			1,450.00	600.00
GRAND TOTAL			3,762.40	751.60
RECOMMENDED COST OF REPAIRS (CONFIRMED)				751.60

Report Ref No. NS/INC21006919/Ntcn2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.