



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3955P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	CRACKED	459.40	459.40
1	REAR BUMPER REINFORCEMENT	DENTED	394.80	394.80
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @ \$138.10	O/S BENT / N/S SERVICEABLE	276.20	138.10
1	REAR BUMPER CENTRE MOULDING ASSY	CRACKED	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	DEFORMED	155.00	155.00
10	REAR BUMPER COVER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER TOW COVER	SERVICEABLE	98.80	-
1	REAR BUMPER FOG LAMP	CRACKED	201.50	201.50
1	REAR SMART KEY ANTENNA	CRACKED	40.50	40.50
	LESS 20% DISCOUNT		-419.89	-372.51
			1,679.56	1,490.04
<u>NETT ITEMS</u>				
1	REAR NO PLATE W/TRIM COVER (N)	CRACKED	55.00	55.00
	LESS 10% DISCOUNT		-5.50	-5.50
			49.50	49.50
<u>LABOUR</u>				
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING.		300.00	250.00
	R/I REVERSE SENSOR.		120.00	30.00
			820.00	630.00
GRAND TOTAL			2,549.06	2,169.54
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,169.54

Report Ref No. NS/INC21006920/Nqcn2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.