

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21006924/UGS3Q2
Date: 15/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070135329
Claimant Vehicle No :	GBK7953Y	Insured Vehicle No :	SLA886M
Date of Loss:	18/06/2021	Nature of Claim:	TP
		Claim No:	8240070636SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK7953Y		
Make & Model:	NISSAN NV200, 1.6 VANETTE DX (A)	Engine No:	HR16174075D
Reg. Date:	26/11/2020 (Man. Year: 2020)	Chassis No:	VM20160870
Colour:	Grey	Odometer:	10853 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	165/80 R14	Rear Tyre Size:	165/80 R14
Front Left Side:	Toyo 7 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,121.12	5,282.59	1,838.53	25.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,300.00	550.00	29.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,971.12	6,582.59	2,388.53	26.62
Approved Total (Overridden) (S\$)		5,250.00		

(S\$)	8,971.12	5,250.00	3,721.12	41.48
+ GST 7.00/7.00% (S\$)	627.98	367.50	260.48	41.48
Nett Amount (S\$)	9,599.10	5,617.50	3,981.60	41.48
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,099.50		

INSPECTION

Date of Assignment: 22/06/2021

Date Inspected: 22/06/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*HEADLAMP	Cracked	1,292.80 FN	*1,258.60 FN
2	1		*O/S HEADLAMP PANEL	Bent / Twisted	80.30 FN	*80.30 FN
3	2		*HEADLAMP LOWER GARNISH	Distorted / Torn	723.00 FN	*723.00 FN
4	1		*RADIATOR GRILLE	Cracked	338.00 FN	*303.30 FN
5	1		*FRONT BUMPER	Distorted	536.10 FN	*536.10 FN
6	1		*FRONT BUMPER REINFORCEMENT	Bent	559.00 FN	*559.00 FN
7	1		*FRONT BUMPER SPONGE	Torn	265.10 FN	*188.90 FN
8	1		*O/S FRONT BUMPER SIDE RETAINER	Bent	22.90 FN	*22.90 FN
9	10		*FRONT BUMPER CLIP	Necessary	44.00 FN	*44.00 FN
10	1		*O/S FRONT FENDER	Buckled	504.70 FN	*504.70 FN
11	1		*O/S FRONT FENDER COWLING	Not Necessary	138.90 FN	*- FN
12	1		*FRONT SUPPORT PANEL	Bent / Twisted	290.20 FN	*290.20 FN
13	1		*FRONT SUPPORT PANEL LOCK	Not Necessary	54.30 FN	*- FN
14	1		*FRONT SUPPORT PANEL LOCK FIBRE	Not Necessary	125.00 FN	*- FN
15	1		*RADIATOR ASSY	Serviceable	687.40 FN	*- FN
16	1		*BONNET	Buckled	830.30 FN	*782.90 FN
17	1		*BONNET HINGE	O/S Bent	109.80 FN	*54.90 FN
18	1		*AIRCON CONDENSER	Not Necessary	658.20 FN	*- FN
19	1		*AIRCON SIDE GARNISH -TOP	Torn	87.90 FN	*87.90 FN
20	1		*AIRCON SIDE GARNISH GUARD	Torn	119.70 FN	*119.70 FN
21	1		*AIR CLEANER DUCT -OUTER	Cracked	83.40 FN	*83.40 FN
22	1		*AIR CLEAN DUCT -INNER	Not Necessary	80.40 FN	*- FN
23	1		*WASHER TANK	Deformed	225.40 FN	*185.30 FN
24	1		*FRONT LICENCE PLATE	Bent	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	7,906.80	5,865.10
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	785.68	582.51
Total Parts (\$\$)	7,121.12	5,282.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	850.00	520.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	750.00	680.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	100.00	20.00
4	TO RUST PROOFING OF THE AFFECTED AREAS	New	150.00	80.00
Gross Labour Cost (S\$)			1,850.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >