

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG21006928/R1RS3Q2  
**Date:** 24/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070140722
<b>Claimant Vehicle No :</b>	SMB1337H	<b>Insured Vehicle No :</b>	SMD668Z
Date of Loss:	17/06/2021	Nature of Claim:	TP
		Claim No:	7522220805SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMB1337H</b>	Engine No:	50345682284567
Make & Model:	MAN NL320F (A22), 10.5 D ABS TURBO (A)	Chassis No:	WMAA22ZZ1D7001783
Reg. Date:	25/03/2013 (Man. Year: 2012)	Odometer:	780042 km
Colour:	Multi-colour		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Firestone 8 mm	Rear Left Side:	Fireenza 8/8 mm
Front Right Side:	Firestone 8 mm	Rear Right Side:	Fireenza 8/8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,861.30	2,962.80	898.50	23.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,251.00	1,986.00	265.00	11.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,112.30</b>	<b>4,948.80</b>	<b>1,163.50</b>	<b>19.04</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,350.00</b>		

<b>Nett Amount (S\$)</b>	<b>6,112.30</b>	<b>4,350.00</b>	<b>1,762.30</b>	<b>28.83</b>
		<hr/>		
<b>+ Loss of Use (3.0 x S\$250.00/day) (S\$)</b>		750.00		
<b>+ Doc/Search Fee (S\$)</b>		7.00		
		<hr/>		
<b>Nett Liability (S\$)</b>		<b>5,107.00</b>		
		<hr/>		

INSPECTION

Date of Assignment: 21/06/2021

Date Inspected: 21/06/2021

Estimated Period of Repair: 3.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)  
60 Woodlands Industrial Park E4  
Singapore 757705

**Adjuster:** MOHD RASUL**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## Recommended Parts

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REINSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,325.00	1,060.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	446.00	446.00
3	ADVERTISEMENT STICKER	New	480.00	480.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,251.00</b>	<b>1,986.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >