

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21006936/NTF3N2**Date:** 04/03/2022**REFERENCE**

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001384473

Claimant Vehicle No : SKF5713G**Insured Vehicle No :** SMF834A

Date of Loss: 21/06/2021

Nature of Claim: TP

Claim No: 258980

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKF5713G**

Make & Model: VOLKSWAGEN TOURAN, 1.4 TSI 1T32B4 (A)

Engine No: CAV406107

Reg. Date: 14/06/2012 (Man. Year: 2012)

Chassis No: WVGZZZ1TZW107934

Colour: Silver

Odometer: 197441 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size: 205/55R16

Front Left Side: Arivo 5 mm

Rear Left Side: Arivo 4 mm

Front Right Side: Arivo 5 mm

Rear Right Side: Arivo 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,329.90	5,523.00	14,806.90	72.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,800.00	1,510.00	6,290.00	80.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	28,129.90	7,033.00	21,096.90	75.00
Approved Total (Overridden) (\$\$)		3,200.00		
(\$\$)	28,129.90	3,200.00	24,929.90	88.62
+ GST 7.00/7.00% (\$\$)	1,969.09	224.00	1,745.09	88.62
Nett Amount (\$\$)	30,098.99	3,424.00	26,674.99	88.62

INSPECTION

Date of Assignment: 23/06/2021

Date Inspected: 23/06/2021 Inspected At:

56 LOYANG WAY

#04-04

REPAIRER: AP AUTOMOTIVE SERVICES PTE LTD

Estimated Period of Repair: 6.0 days

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2022)
Parts:	M1-MPV	VOLKSWAGEN TOURAN 1.4 TSI 1T32B4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF5713G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,352.00 FL	*1,000.00 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	316.00 FL	*316.00 FL
3	1		*TAILGATE LOGO-VOLKSWAGEN	Necessary	79.00 FL	*50.00 FL
4	1		*TAILGATE EMBLEM-TOURAN	Necessary	77.00 FL	*50.00 FL
5	1		*TAILGATE EMBLEM-TSI	Necessary	69.00 FL	*50.00 FL
6	2		*TAILGATE LAMP L+R	Serviceable	1,045.00 FL	*- FL
7	1		*TAILGATE LOCK	Serviceable	376.00 FL	*- FL
8	1		*TAILGATE LOCK CATCH	Serviceable	79.00 FL	*- FL
9	1		*TAILGATE INNER TRIM	Serviceable	882.00 FL	*- FL
10	1		*TAILGATE WEATHERSTRIP	Torn	532.00 FL	*300.00 FL
11	2		*TAIL LAMP L+R	Cracked	1,468.00 FL	*800.00 FL
12	2		*TAIL LAMP LOWER BRACKET L+R	Cracked	168.00 FL	*168.00 FL
13	1		*REAR BUMPER	Cracked	1,060.00 FL	*750.00 FL
14	2		*REAR BUMPER REFLECTOR L+R	Cracked	356.00 FL	*356.00 FL
15	1		*REAR BUMPER REVERSE SENSOR SET	Deformed	1,486.00 FL	*600.00 FL
16	1		*REAR BUMPER TOW COVER	Serviceable	59.00 FL	*- FL
17	2		*REAR FENDER L+R	Serviceable	2,410.00 FL	*- FL
18	2		*REAR FENDER INNER TRIM L+R	Serviceable	1,352.00 FL	*- FL
19	1		*REAR FENDER COWLING L+R	O/s Torn/N/s Serviceable	552.00 FL	*276.00 FL
20	1		*END PANEL	Repair	698.00 FL	*- FL
21	1		*END PANEL TOP GARNISH	Cracked	170.00 FL	*170.00 FL
22	1		*FLOOR PANEL	Serviceable	1,203.00 FL	*- FL
23	1		*FLOOR PANEL TOP BOARD	Serviceable	674.00 FL	*- FL
24	1		*EXHAUST PIPE	Serviceable	789.00 FL	*- FL
25	1		*EXHAUST MOUNTING SET	Serviceable	49.00 FL	*- FL
26	1		*EXHAUST HEAT SHIELD	Serviceable	321.00 FL	*- FL
27	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*80.00 FS
28	1		*TAILGATE INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
29	1		*REVERSE CAMERA	Serviceable	800.00 FS	*- FS
30	1		*REAR NUMBER PLATE	Serviceable	120.00 FS	*- FS
31	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*50.00 FS
32	1		*REAR BUMPER CENTER BRACKET	Cracked	276.00 FL	*276.00 FL
33	2		*REAR BUMPER RETAINER L+R	Cracked	432.00 FL	*280.00 FL
34	1		*REAR BUMPER REINFORCEMENT BAR	Bent	428.00 FL	*428.00 FL
35	1		*FLOOR PANEL ACCESSORIES TRAY	Serviceable	453.00 FL	*- FL
36	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*60.00 FS
37	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	200.00 FS	*- FS
38	1		*REAR FENDER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
39	1		*END PANEL SEALANT	Not Necessary	200.00 FS	*- FS
40	1		*END PANEL TOP GARNISH CLIPS	Necessary	100.00 FS	*50.00 FS
41	1		*FLOOR PANEL SEALANT	Not Necessary	250.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					22,351.00	6,110.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					2,021.10	587.00
Total Parts (\$\$)					20,329.90	5,523.00

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,400.00	500.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,600.00	600.00
3	TO RNR REAR WINDSCREEN	New	400.00	120.00
4	TO RNR REAR EXHAUST	New	250.00	60.00
5	TO CHECK WIRING AND TAIL LAMP FUNCTION }	New	150.00	50.00
6	TO CHECK WIRING AND TAIL GATE LAMP FUNCTION }	New	150.00	0.00
7	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	0.00
8	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	0.00
9	TO RNR UNDERCARRIAGE	New	250.00	0.00
10	TO CHECK WATER LEAK	New	150.00	0.00
11	TO RNR FUEL TANK	New	250.00	0.00
12	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
13	TO RNR REAR TAILGATE MECHANISM	New	400.00	50.00
14	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
15	TO PERFORM RUST PROOFING	New	400.00	100.00
Gross Labour Cost (\$\$)			7,800.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >