

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21006937/ATCN2**Date:** 13/10/2021**REFERENCE**

Insured/Claimant:	SIMON ONG ENG HOCK	Policy No:	1800097216
Date of Loss:	16/06/2021	Nature of Claim:	OD
		Claim No:	0113089844SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD3242Z	Engine No:	CVK064806
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Chassis No:	WAUZZZF4XJN015523
Reg. Date:	14/08/2018 (Man. Year: 2018)	Odometer:	31487 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,291.00	9,014.40	14,276.60	61.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,122.00	5,892.00	14,230.00	70.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,413.00	14,906.40	28,506.60	65.66
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	42,863.00	14,356.40	28,506.60	66.51
+ GST 7.00/7.00% (S\$)	3,000.41	1,004.95	1,995.46	66.51
Nett Amount (S\$)	45,863.41	15,361.35	30,502.06	66.51

INSPECTION

Date of Assignment:	23/06/2021		
Date Inspected:	22/06/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,181.00 FS	*1,744.80 FS
2	1		*REAR BUMPER GUIDE SECTION-LH	Not Necessary	44.00 FS	*- FS
3	1		*REAR SECTIONAL PART-LH	Repair	4,052.00 FS	*- FS
4	1		*REAR WINDSCREEN	Not Necessary	1,154.00 FS	*- FS
5	1		*REAR 1/4 GLASS-LH	Not Necessary	616.00 FS	*- FS
6	1		*REAR DOOR-LH	Dented	3,192.00 FS	*2,553.60 FS
7	1		*REAR DOOR OUTER SEAL-LH	Necessary	205.00 FS	*164.00 FS
8	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
9	1		*CLEANING COLUTION	Not Necessary	68.00 FS	*- FS
10	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
11	1		*REAR DOOR SEALING STRIP	Not Necessary	17.00 FS	*- FS
12	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	0.00 FS	*- FS
			NPA			
13	1		*REAR DOOR CATCH-LH	Damaged	120.00 FS	*96.00 FS
14	1		*FRONT DOOR-LH	Dented	3,192.00 FS	*2,553.60 FS
15	1		*FRONT DOOR OUTER SEAL-LH	Necessary	205.00 FS	*164.00 FS
16	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
17	1		*CLEANING COLUTION	Not Necessary	68.00 FS	*- FS
18	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
19	1		*BUNGS	Not Necessary	4.00 FS	*- FS
20	1		*FRONT DOOR ATTACHMENT PARTS-LH	Not Necessary	0.00 FS	*- FS
			NPA			
21	1		*FRONT DOOR CATCH-LH	Not Necessary	105.00 FS	*- FS
22	1		*REAR WHEEL HOUSING-LH	Repair	240.00 FS	*- FS
23	1		*REAR WHEEL HOUSING ATTACHMENT PARTS	Not Necessary	0.00 FS	*- FS
			NPA			
24	1		*REAR TAIL LIGHT-OUTER LH	Cut	1,019.00 FS	*815.20 FS
25	1		*REAR TAIL LIGHT TRIM-OUTER LH	Not Necessary	30.00 FS	*- FS
26	1		*REAR TYRE RIM-LH	Cut	1,142.00 FS	*913.60 FS
27	4		*REAR WISHBONE-LH LOWER/UPPER/FRONT/REAR	Not Necessary	1,985.00 FS	*- FS
28	1		*REAR TRACK ROD-LH	Not Necessary	171.00 FS	*- FS
29	1		*REAR WHEEL BEARING HOUSING-LH	Not Necessary	990.00 FS	*- FS
30	1		*REAR WHEEL BEARING-LH	Not Necessary	440.00 FS	*- FS
31	1		*REAR STONE CHIP GUARD-LH	Not Necessary	45.00 FS	*- FS
32	1		*REAR ABSORBER-LH	Not Necessary	301.00 FS	*- FS
33	1		*REAR BUMPER REFLECTOR	Not Necessary	41.00 FS	*- FS
34	1		*REAR WINDSCREEN PRIMER	Not Necessary	20.00 FS	*- FS
35	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
36	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
37	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
38	1		*STONE CHIP TREATMENT	Not Necessary	180.00 FS	*- FS
39	1		*METAL FILLER POWER	Not Necessary	280.00 FS	*- FS
40	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
41	1		*SUNDRIES	Necessary	450.00 FS	*9.60 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 23,291.00 9,014.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	0.00
2	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND LHS 1/4 GLASS	New	400.00	0.00
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS	New	200.00	0.00
5	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHT,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT.INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	0.00
6	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS.DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
7	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	700.00	560.00
8	TO REMOVE AND RENEW LHS REAR WHEEL SUSPENSION ASSEMBLY	New	1,800.00	0.00
9	TO DISMANTLE AND RENEW BUMPER.LHS REAR DOOR AND LHS FRONT DOOR.TO CUT OUT AND WELD LHS REAR FENDER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	6,300.00	1,750.00
10	TO RESPRAY REAR BUMPER,LHS REAR FENDER,LHS REAR DOOR,LHS FRONT DOOR.TO CUT OUT AND WELD LHS REAR FENDER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	6,250.00	2,750.00
11	TO RENEW LHS REAR RIM.TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	280.00
12	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			20,122.00	5,892.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >