

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111

FAX: 62247175

ATTN: Motor Claim Department

Estimate No: **EST2100159**
Date: 21 Jun 2021

Veh Reg No: **SKJ5699T**
Make/Model: VOLVO V40 CROSS
COUNTRY T4

Chasis No: YV164T1129860

Reg. Date: 19/04/2013

Your Ref No: GBJ9132S

Claim Type: Third Party

Accident Date: 20/06/2021

TP Veh Reg No: GBJ9132S

Estimate Repair Cost to Vehicle No :SKJ5699T

Quantity	Description	List Price SS	Amount SS
	List Price	2,720.00	1650
1	1 PC BONNET <i>Dented</i>	207.20	x
2	2 PCS BONNET HINGES <i>new</i>	212.70	+
3	1 PC BONNET LOCK RH <i>new</i>	212.70	+
4	1 PC BONNET LOCK LH	1,540.80	-
5	1 PC FRT BUMPER <i>Distorted</i>	567.90	-
6	1 PC FRT BUMPER REINFORCEMENT <i>Dented</i>	248.20	124.10
7	2 PCS FRT BUMPER BRACKETS <i>RH Bent</i>	168.20	2
8	1 PC FRT BUMPER GRILLE <i>crack</i>	303.70	-
9	1 PC FRT BUMPER INNER CENTRE BEAM <i>Bent</i>	126.70	✓
10	1 PC FRT BUMPER INNER RETAINER - RH <i>Dented</i>	126.70	+
11	1 PC FRT BUMPER INNER RETAINER - LH <i>new</i>	198.20	99.10
12	2 PCS FRT BUMPER SIDE RETAINERS <i>RH Dented</i>	363.10	✓
13	1 PC FRT BLACK SIDE BUMPER RH <i>Dented</i>	363.10	+
14	1 PC FRT BLACK SIDE BUMPER LH <i>new</i>	356.70	✓
15	1 PC FRT FOG LAMP RH <i>crack</i>	356.70	+
16	1 PC FRT FOG LAMP LH <i>new</i>	494.20	✓
17	1 PC FRT LOWER BUMPER <i>Dented</i>	387.90	+
18	1 PC FRT BUMPER LOWER PROTECTOR <i>new</i>	494.80	✓
19	1 PC FRT BUMPER LOWER GARNISH <i>torn</i>	49.20	+
20	1 PC FRT BUMPER TOWING COVER <i>new</i>	207.80	+
21	1 PC FRT BUMPER LIP GARNISH <i>new</i>	634.90	✓
22	1 PC FRT GRILLE <i>crack</i>	203.90	✓
23	1 PC FRT GRILLE VOLVO EMBLEM <i>new</i>	266.90	✓
24	1 PC FRT GRILLE INNER AIR VENT COVER <i>Dented</i>	1,972.90	1750
25	1 PC FRT SUPPORT PANEL <i>Dented crack</i>	989.70	✓
26	1 PC HEADLAMP RH <i>crack</i>	102.20	+
27	1 PC FRT HEAD LAMP BRACKET RH <i>new</i>	177.40	✓
28	1 PC HORN RH <i>Dented</i>	78.90	✓
29	1 PC HORN BRACKET RH <i>Bent</i>		
	1 PC Engine under cover <i>torn</i>		285

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST2100159

Date: 21 Jun 2021

Veh Reg No: SKJ5699T
Make/Model: VOLVO V40 CROSS
COUNTRY T4

Chasis No: YV164T1129860

Reg. Date: 19/04/2013

Your Ref No: GBJ9132S

Claim Type: Third Party

Accident Date: 20/06/2021

TP Veh Reg No: GBJ9132S

Estimate Repair Cost to Vehicle No :SKJ5699T

Quantity	Description	List Price	Amount
		SS	SS
30	1 PC HEADLAMP LH <i>new</i>	989.70	+
31	1 PC HEADLAMP BRACKET LH <i>new</i>	102.20	+
32	1 PC FRT FENDER COWLING RH <i>torn</i>	314.20	+
33	1 PC FRT WIPER WATER TANK <i>dented</i>	187.60	+
34	1 PC FRONT WIPER WATER TANK MOTOR <i>new</i>	141.20	+
35	1 PC FRT TURBO <i>Dented</i>	2,680.30	2
36	1 PC FRT TURBO OUTER GARNISH <i>cracked</i>	303.60	+
37	1 PC AIRCON CONDENSER <i>new</i>	1,473.80	+
38	1 PC AIR CON OUTER GARNISH <i>new</i>	169.30	+
39	1 PC FRT FOG LAMP WIRE HARNESS <i>new</i>	427.60	+
		20,922.80	
	Less 10%	2,092.28	18,830.52
Special Net			
40	1 SET FRT BUMPER GRILLE CLIPS <i>new</i>	30.00	20
41	1 SET FRT BUMPER INNER CENTRE TRIM CLIPS <i>new</i>	40.00	20
42	1 SET FRT BUMPER CLIPS <i>new</i>	60.00	30
43	1 SET FRT BUMPER LOWER GARNISH CLIPS <i>new</i>	40.00	30
44	1 PC FRT NUMBER PLATE <i>new</i>	50.00	+
45	1 SET FRT GRILLE CLIPS <i>new</i>	30.00	20
46	1 SET FRT FENDER COWLING CLIPS RH <i>new</i>	40.00	30
47	1 SET RADIATOR UNDER COVER CLIPS <i>new</i>	40.00	+
48	1 SET FRT BUMPER LOWER PROTECTOR CLIPS <i>new</i>	40.00	+
		370.00	370.00
Labour			
49	1 TO REMOVE AND REPLACE THE FRONT DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,300.00	900
50	1 TO SPRAY PAINTING	1,300.00	500
51	1 TO SPRAY UNDERSEAL	120.00	+

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 20/06/2021
TP Veh Reg No: GBJ9132S

Estimate No: EST2100159

Date: 21 Jun 2021

Veh Reg No: SKJ5699T
Make/Model: VOLVO V40 CROSS
COUNTRY T4

Chasis No: YV164T1129860

Reg. Date: 19/04/2013

Your Ref No: GBJ9132S

Estimate Repair Cost to Vehicle No :SKJ5699T

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
52	1 TO REFILL AIRCON GAS	120.00 ✓	
53	1 TO CHECK WIRING	50.00 30	
		2.890.00	2.890.00
		Total	S\$ 22,090.52
		Add GST @ 7%	1,546.34
		Total Amount Payable	<u>S\$ 23,636.86</u>

TOTAL: SINGAPORE DOLLAR TWENTY THREE THOUSAND SIX HUNDRED THIRTY SIX AND CENTS EIGHTY SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

total: 15733.37

L/S: 12-6K.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Adrian L

Adrian L
L/S 22/06/21.

0 T Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date: