8/20/2021 Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21006946/EVCN2

20/08/2021 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMCVSNW00053402103

**Claimant Vehicle** No:

PC4408B

Insured Vehicle No:

GBG1043J

Date of Loss:

21/06/2021

Nature of Claim: TP

Odometer:

SNM21D203506/C02/TOHHS

285473 km

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

PC4408B Reg No:

YUTONG ZK6938H, 6.7 D AUTOEU6 (M) ISB67E525022171530 Make & Model: Engine No: Reg. Date: 01/02/2016 (Man. Year: 2015) Chassis No: LZYTCTD67F1064161

Colour: Multi-colour

**Engine Capacity:** 6690 cc N/A

Market Value/New Car Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 295/80R22.5 Rear Tyre Size: 295/80R22.5 Front Left Side: Rear Left Side: Bridgestone 5 mm Bridgestone 5 mm Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,365.00	7,645.00	2,720.00	26.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,510.00	3,030.00	1,480.00	32.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,875.00	10,675.00	4,200.00	28.24
+ GST 7.00/7.00% (S\$)	1,041.25	747.25	294.00	28.24
Nett Amount (S\$)	15,916.25	11,422.25	4,494.00	28.24

**INSPECTION** 

Date of Assignment: 24/06/2021

Connect3 (woodlands) (HQ) 566 Woodlands Road Date Inspected: 24/06/2021 Inspected At:

Singapore 7286970

Estimated Period of Repair: 6.0 days

Adjuster: **CHEN TSUE YEE** Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$860.00 NETT) 8/20/2021 Adjuster Report

### **REPAIR DETAILS**

Reference

Part Source: (Last Synchronised: 20 Aug 2021)

Parts: N/A YUTONG ZK6938H 6.7 D AUTOEU6 (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PC4408B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,850.00 F	*1,850.00 F
2	1		*REAR BUMPER INNER STRUCTURE	Dented	780.00 F	*780.00 F
3	2		*REAR BUMPER BRACKET LH & RH	Necessary	500.00 F	*500.00 F
4	1		*REAR EXHAUST TIP	Not Necessary	650.00 F	*- F
5	1		*REAR EXHAUST TIP BRACKET	Not Necessary	80.00 F	*- F
6	2		*REAR TAILGATE HINGES	Not Necessary	560.00 F	*- F
7	1		*REAR TAILGATE OUTER PANEL	Dented	3,800.00 F	*3,800.00 F
8	1		*REAR TAILGATE RUBBER MOULDING	Not Necessary	550.00 F	*- F
9	2		*REAR TAILGATE CURVE LAMP	*Check	860.00 F	*- F
10	1		*REAR NUMBER PLATE	Broken	40.00 F	*40.00 F
11	1		*60KM/H STICKER	Necessary	15.00 F	*15.00 F
12	1		*REVERSE SENSOR (1 SET-4 PCS)	Broken	300.00 F	*300.00 F
13	1		*EMBLEM YUTONG	Necessary	180.00 F	*180.00 F
14	1		*ZK6838H EMBLEM	Necessary	180.00 F	*180.00 F
15	1		*TEST REVERSE SENSOR	Not Necessary	20.00 F	*- F
F=Fra	ınchise	part.		Total Parts (S\$)	10,365.00	7,645.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	our Items					
1	LABOUR TO REMOVE & REFIT REAR EXHAUST TIP	New	150.00	0.00		
2	LABOUR CHARGES	New	2,100.00	1,200.00		
3	SPRAY PAINTING (MULTI COLOR WITH FADED EFFECT	) New	2,200.00	1,800.00		
4	CHECK WIRING	New	60.00	30.00		
		Gross Labour Cost (S\$)	4,510.00	3,030.00		
Report was unsubmitted during this print-out.						

< END OF ESTIMATES >