1/30/23, 11:16 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21006948/ANY3Q2

30/01/2023 Date:

MM000365

**REFERENCE** 

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No:

**Claimant Vehicle** SMC4112P Insured Vehicle No: SMZ8874B No:

Date of Loss: 16/06/2021 Nature of Claim: TP Claim No: M2102869

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SMC4112P** 

Make & Model: TOYOTA C-HR, 1.8 S (A) 2ZR8085735 Engine No: Reg. Date: 29/06/2018 (Man. Year: 2017) Chassis No: ZYX102031938 214250 km Colour: Odometer: Black

**Engine Capacity:** 1797 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

215/55 R17 Front Tyre Size: 215/55 R17 Rear Tyre Size: Front Left Side: RAPID 6 mm Rear Left Side: RAPID 6 mm Front Right Side: RAPID 6 mm Rear Right Side: RAPID 6 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
4,066.47	2,508.22	1,558.25	38.32
0.00	0.00	0.00	
2,830.00	1,260.00	1,570.00	55.48
0.00	0.00	0.00	
0.00	0.00	0.00	
6,896.47	3,768.22	3,128.25	45.36
	3,000.00		
6,896.47	3,000.00	3,896.47	56.50
551.72	240.00	311.72	56.50
7,448.19	3,240.00	4,208.19	56.50
	4,066.47 0.00 2,830.00 0.00 0.00 <b>6,896.47</b> 6,896.47 551.72	4,066.47 2,508.22 0.00 0.00 2,830.00 1,260.00 0.00 0.00 0.00 0.00 6,896.47 3,768.22 3,000.00 6,896.47 3,000.00 551.72 240.00	4,066.47 2,508.22 1,558.25   0.00 0.00 0.00   2,830.00 1,260.00 1,570.00   0.00 0.00 0.00   0.00 0.00 0.00   6,896.47 3,768.22 3,128.25   3,000.00 3,896.47   551.72 240.00 311.72

**INSPECTION** 

Date Inspected:

Date of Assignment: 17/06/2021

MG Solution Pte Ltd (HQ)

23 Kaki Bukit Avenue 4 #02-03B, VICOM 18/06/2021 Inspected At:

Inspection Centre Singapore 415933

Estimated Period of Repair: 5.0 days

Adjuster: **ADRIAN LING** Manager: **HUEY YON** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Jan 2023)

Parts: M1-SUV TOYOTA C-HR 1.8 S (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMC4112P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	1,366.90 FL	*- FL
2	1		*BOOTLID DETECTOR	Cracked	280.30 FL	*175.00 FL
3	1		*BOOTLID WINDSCREEN MOULDING	Not Necessary	211.30 FL	*- FL
4	1		*REAR BUMPER	Deformed	850.00 FL	*850.00 FL
5	1		*REAR BUMPER LOWER LID	Deformed	420.00 FL	*420.00 FL
6	2		*REAR BUMPER SIDE RETAINER	Necessary	124.80 FL	*124.80 FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	555.00 FL	*338.00 FL
8	1		*REAR BUMPER TOWING COVER	Deformed	66.50 FL	*36.00 FL
9	1		*REAR BUMPER BRAKELIGHT HOUSING	Cracked	90.00 FL	*90.00 FL
10	1		*REAR END PANEL	Dented	680.00 FL	*680.00 FL
11	1		*REAR END PANEL TOP GARNISH	Deformed	230.50 FL	*230.50 FL
12	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
13	1		*BOOTLID WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
14	1		*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
15	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
16	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
17	1		*REVERSE SENSOR	Damaged	200.00 FS	*200.00 FS
F=Fra	anchise	part. S=SpcN	lett. L=ListItemDisc.	-		
				Sub Total (S\$)	5,285.30	3,244.30
			- List Item Discount on L It	tems 25.00/25.00% (S\$)	1,218.83	736.08
				Total Parts (S\$)	4,066.47	2,508.22

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,200.00	500.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	600.00
3	TUFF COAT	New	60.00	40.00
4	WIRING CHECK	New	30.00	30.00
5	UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	60.00	40.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	50.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	50.00	0.00
8	TRANSFER BOOT LID MECHANISM	New	60.00	0.00
9	TO REMOVE AND REFIX REAR WINDSCREEN	New	120.00	0.00
	Gross Labor	ur Cost (S\$)	2,830.00	1,260.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >