

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21006949/EVF3E2

Date: 02/07/2021

REFERENCE

Insured/Claimant:	TANG KAH PING	Policy No:	2070149027		
Date of Loss:	22/06/2021	Nature of Claim:	OD	Claim No:	5981510330SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV9778K		
Make & Model:	MITSUBISHI ECLIPSE CROSS, 1.5 (A)	Engine No:	4B40HB6423
Reg. Date:	29/10/2020 (Man. Year: 2019)	Chassis No:	JMAXTGK1WLZ000785
Colour:	Red	Odometer:	24258 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	S\$113,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,574.00	6,786.00	9,788.00	59.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,100.00	4,570.00	7,530.00	62.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	28,674.00	11,356.00	17,318.00	60.40
+ GST 7.00/7.00% (S\$)	2,007.18	794.92	1,212.26	60.40
Nett Amount (S\$)	30,681.18	12,150.92	18,530.26	60.40

INSPECTION

Date of Assignment:	23/06/2021	
Date Inspected:	23/06/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	9.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$7,990.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
2	1		*REAR BUMPER PLATE WITH FRAME	Cut	50.00 FS	*50.00 FS
3	1		*REAR IN CAR CAMERA	Missing	680.00 FS	*680.00 FS
4	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
5	1		*FACE, RR BUMPER	Dented	556.00 F	*556.00 F
6	1		*EXTENSION, RR BUMPER	Broken	152.00 F	*152.00 F
7	1		*COVER, RR BUMPER, RH	Broken	117.00 F	*117.00 F
8	1		*COVER, RR BUMPER, LH	Cut	117.00 F	*117.00 F
9	1		*BRKT, R/BMPR FACE SIDE, RH	* Check	25.00 F	*- F
10	1		*BRKT, R/BMPR FACE SIDE, LH	Broken	25.00 F	*25.00 F
11	1		*BRACKET, RR BUMPER SIDE, LWR	* Check	12.00 F	*- F
12	1		*REINFORCEMENT, RR BUMPER	* Check	497.00 F	*- F
13	1		*CORE, RR BUMPER	* Check	34.00 F	*- F
14	1		*CORE, RR BUMPER	* Check	41.00 F	*- F
15	1		*EXTN, QTR PANEL, RR LWR LH	* Check	97.00 F	*- F
16	1		*REINF, GATE PILLAR, LH	Not Necessary	150.00 F	*- F
17	1		*PANEL, QTR, OTR LH	Repair	866.00 F	*- F
18	1		*PANEL, RR END	* Check	475.00 F	*- F
19	1		*PANEL, RR END, INR LH	* Check	137.00 F	*- F
20	1		*PANEL, RR END, INR RH	* Check	137.00 F	*- F
21	1		*BRAKE, RR FLOOR SIDE, LH	* Check	33.00 F	*- F
22	1		*SHIELD, RR WHEEL, RR LH	* Check	38.00 F	*- F
23	1		*PANEL ASSY, TAILGATE	Dented	984.00 F	*984.00 F
24	2		*HINGE, TAILGATE	* Check	58.00 F	*- F
25	1		*GAS SPRING, TAILGATE, RH	* Check	148.00 F	*- F
26	1		*GAS SPRING, TAILGATE, LH	* Check	148.00 F	*- F
27	1		*W/STRIP, TAILGATE OPENING	* Check	194.00 F	*- F
28	1		*GLASS, TAILGATE WINDOW	Not Necessary	706.00 F	*- F
29	8		*FASTENER, WINDSHIELD	Necessary	48.00 F	*48.00 F
30	2		*STOPPER, WINDSHIELD GLASS	Necessary	6.00 F	*6.00 F
31	2		*SPACER, QTR WINDOW	Necessary	16.00 F	*16.00 F
32	2		*SPACER, QTR WINDOW	Necessary	16.00 F	*16.00 F
33	2		*SPACER, TAILGATE	Necessary	16.00 F	*16.00 F
34	2		*SPACER, TAILGATE	Necessary	16.00 F	*16.00 F
35	1		*DAM, TAILGATE, LWR	Necessary	13.00 F	*13.00 F
36	1		*GLASS, TAILGATE WINDOW	Broken	524.00 F	*524.00 F
37	1		*GARNISH, TAILGATE	Crushed	490.00 F	*490.00 F
38	1		*LATCH, TAILGATE	* Check	385.00 F	*- F
39	1		*HANDLE, TAILGATE LOCK RLSE	* Check	201.00 F	*- F
40	1		*TRIM, TAILGATE, LWR	Crushed	402.00 F	*402.00 F
41	1		*MOULDING, R/DOOR PROTECT, LH	* Check	105.00 F	*- F
42	1		*GARNISH, QTR PANEL, LH	* Check	181.00 F	*- F
43	1		*MARK, ECLIPSE CROSS	Necessary	87.00 F	*87.00 F
44	1		*MOULDING, RR WHEEL ARCH, LH	* Check	153.00 F	*- F
45	1		*TRIM, RR SHELF	* Check	578.00 F	*- F
46	1		*TRIM, RR END	* Check	122.00 F	*- F
47	1		*LID, CARGO FLOOR BOX	* Check	324.00 F	*- F
48	1		*LAMP ASSY, COMB, RR LH	Broken	693.00 F	*693.00 F
49	1		*LAMP ASSY, COMB, RR RH	* Check	693.00 F	*- F
50	1		*LAMP ASSY, STOP & TAIL	Broken	1,118.00 F	*1,118.00 F
51	1		*LAMP ASSY, LICENSE PLATE	* Check	34.00 F	*- F
52	1		*LAMP ASSY, FOG, RR RH	* Check	132.00 F	*- F
53	1		*MOTOR, RR WINDOW WIPER (*)	* Check	462.00 F	*- F
54	1		*BLADE ASSY, RR WINDOW WIPER	Not Necessary	32.00 F	*- F
55	1		*ARM ASSY, RR WINDOW WIPER	Not Necessary	44.00 F	*- F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*BUZZER, KEYLESS OPERATIO, RR	* Check	91.00 F	*- F
57	1		*ANT, KEYLESS OPERATION, RR	* Check	96.00 F	*- F
58	1		*SENSOR, BACK DISTANCE WARN	* Check	329.00 F	*- F
59	1		*SENSOR, CORNER CLEARANCE	* Check	333.00 F	*- F
60	1		*SENSOR, CORNER CLEARANCE	* Check	333.00 F	*- F
61	1		*HARNESS, RR BUMPER	* Check	220.00 F	*- F
62	1		*HARNESS, TAILGATE	* Check	306.00 F	*- F
63	1		*CAMERA, RR VIEW	* Check	681.00 F	*- F
64	1		*DUCT, RR VENTILATOR	* Check	39.00 F	*- F
65	1		*MUFFLER, EXHAUST MAIN	Dented	600.00 F	*600.00 F
66	1		*LAMP ASSY, BACKUP, LH	* Check	118.00 F	*- F

F=Franchise part. S=SpcNett.

Total Parts (S\$)					16,574.00	6,786.00
-------------------	--	--	--	--	-----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR BUMPER, TAILGATE, REAR END PANEL, LAMP HOUSING LH. REPAIR REAR FENDER LH	New	4,480.00	1,350.00
2	REMOVE & INSTALL TAILGATE TOP GLASS	New	300.00	240.00
3	REMOVE & INSTALL TAILGATE LOWER GLASS	New	300.00	240.00
4	REMOVE & INSTALL TAILGATE TRIMS AND REAR COMPARTMENT TRIMS	New	400.00	300.00
5	REMOVE & INSTALL PARKING SENSOR	New	80.00	80.00
6	REMOVE & INSTALL REVERSE CAMERA	New	150.00	120.00
7	SPRAY PAINT FOR REAR BUMPER, TAILGATE, REAR FENDER LH, REAR LAMP HOUSING LH, REAR END PANEL, SPOILER	New	3,850.00	1,440.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	280.00	120.00
9	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
10	APPLY SEALANT FOR TAILGATE BOTH GLASS	New	160.00	160.00
11	APPLY SEALANT FOR ACCIDENT PORTION	New	120.00	40.00
12	PAINT PROTECTION FOR ACCIDENT AFFECTED AREA	New	750.00	0.00
13	TAILGATE TOP GLASS FOLAR FILM	New	240.00	0.00
14	TAILGATE LOWER GLASS FOLAR FILM	New	240.00	150.00
15	REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR	New	300.00	0.00
16	RENEW EXHAUST MUFFLER ASSY	New	300.00	300.00
17	TOWING FEE	New	120.00	0.00
Gross Labour Cost (\$\$)			12,100.00	4,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >