



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 8181K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET INNER LOCK	TO REPAIR SEE LABOUR	101.60	-
1	HEADLAMP ASSEMBLY [HID] O/S	BROKEN	3,250.00	3,250.00
1	HEADLAMP LOWER BRACKET O/S	BENT	39.00	39.00
1	FRONT BUMPER	DENTED	785.00	785.00
1	FRONT BUMPER CENTRE GRILLE	BROKEN	325.00	155.10
1	FRONT BUMPER CENTRE GRILLE TOP SEAL	NECESSARY	12.00	12.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	438.00	-
2	FRONT BUMPER UNDER SPLASH SHIELD	SERVICEABLE	146.00	-
1	FRONT FENDER O/S	TO REPAIR SEE LABOUR	725.00	-
1	FRONT FENDER SPLASH SHIELD O/S	SERVICEABLE	189.00	-
1	FRONT WINDSCREEN RESERVOIR	SERVICEABLE	231.00	-
	LESS 25% DISCOUNT		-	-1,060.28
			6,241.60	3,180.82
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP / FASTENER (SN)	NECESSARY	40.00	30.00
1	FRONT FENDER SPLASH SHIELD CLIP / FASTENER O/S (SN)	NECESSARY	30.00	20.00
1	FRONT ALLOY RIM O/S (SN)	SERVICEABLE	420.00	-
1	FRONT TYRE [YOKOHAMA : 215/55R17] O/S (SN)	SERVICEABLE	250.00	-
			740.00	50.00
<u>LABOUR</u>				
	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT & CHECK FUNCTIONS INCLUDING TO FOCUS HEADLAMPS.		50.00	30.00
	TO DISMANTLE / INSTALL AIR CONDITIONER CONDENSER & RADIATOR ASSEMBLY, PIPES & HOSES ETC TO FACILITATE REPAIRS & REFILL WITH REFRIGERANT [CLIMATISER R134A SPECIFICATION] & COOLANT RESPECTIVELY.	NOT NECESSARY	150.00	-

Report Ref No. CS3/LPC21006951/Buf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CORRECT FRONT WHEEL GEOMETRY INCLUDING TO OSCILLATE / EQUIPOISE O/S FRONT ALLOY RIM / TYRE TO SPECIFICATIONS.		120.00	60.00
	TO DISMANTLE / RENEW THF FRONT ACCIDENT DAMAGED PORTIONS. TO HEAT, KNOCK-OUT, RESHAPE, STRAIGHTEN, ORIENTATE BONNET INNER LOCK / BRIDGE PANEL, FRONT BUMPER BEAM, FRONT BUMPER BRACKET O/S, FRONT FENDER O/S, FRONT SUPPORT PANEL, HEADLAMP PANEL O/S ETC TO SYMMETRICAL DISMENSIONS. INCLUSIVE OF THE REPAIR OF BONNET INNER LOCK, FRONT BUMPER REINFORCEMENT AND FRONT FENDER O/S.		850.00	500.00
	TO PUTTY / PRIMER APPLICATION AND SPRAY PAINTING INCLUDING TOUCH-UP AFFECTED AREAS WITH POLYURETHANE PAINT. }		850.00	300.00
	TO DO RUSTPROOFING AND CAVITIES PRESERVATION TO THE REPLACED AND REPAIRED PANELS. }		-	-
			2,020.00	890.00
GRAND TOTAL			9,001.60	4,120.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,300.00

Report Ref No. CS3/LPC21006951/Buf3e2

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.