

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21006958/UPA3Q2
Date: 16/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SMU6999P	Insured Vehicle No :	GBC3300A
Date of Loss:	20/06/2021	Nature of Claim:	TP
		Claim No:	2292358174SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU6999P	Engine No:	2AZE119358
Make & Model:	TOYOTA CAMRY, 2.4 ABS AIRBAG (A)	Chassis No:	MR053BK4007031125
Reg. Date:	11/02/2009 (Man. Year: 2008)	Odometer:	102933 km
Colour:	Grey		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45Z R18	Rear Tyre Size:	225/45Z R18
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,753.14	8,490.59	2,262.55	21.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	1,580.00	730.00	31.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,063.14	10,070.59	2,992.55	22.91
Approved Total (Overridden) (S\$)		8,000.00		

(S\$)	13,063.14	8,000.00	5,063.14	38.76
+ GST 7.00/7.00% (S\$)	914.42	560.00	354.42	38.76
Nett Amount (S\$)	13,977.56	8,560.00	5,417.56	38.76
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 23/06/2021

Date Inspected: 23/06/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Automobile Integrated Management Pte Ltd (HQ)
 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing)
 Singapore 415933

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented / Buckled	1,265.10 FL	*1,265.10 FL
2	2		*BONNET HINGES	Repair	105.20 FL	*- FL
3	1		*BONNET INSULATOR	Deformed	288.20 FL	*288.20 FL
4	1		*SET BONNET INSULATOR CLIPS	Necessary	50.00 FL	*50.00 FL
5	1		*BONNET LOCK	Twisted	95.50 FL	*95.50 FL
6	1		*FRONT BUMPER	Distorted	522.10 FL	*522.10 FL
7	1		*FRONT BUMPER SPONGE	Torn	115.20 FL	*115.20 FL
8	1		*FRONT BUMPER REINFORCEMENT	Repair	340.90 FL	*- FL
9	2		*FRONT BUMPER CHROME MOULDINGS	Not Necessary	130.00 FL	*- FL
10	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	110.00 FL	*- FL
11	1		*FRONT BUMPER FOG LAMP O/S	Not Necessary	388.50 FL	*- FL
12	1		*FRONT GRILLE	Broken	439.52 FL	*439.52 FL
13	2		*HEADLAMP HIDS	N/S Cracked / O/S Broken	4,500.20 FL	*4,500.20 FL
14	1		*FRONT SUPPORT PANEL	Bent / Twisted	545.20 FL	*545.20 FL
15	1		*FRONT BRACE PANEL	Twisted	121.00 FL	*121.00 FL
16	1		*CONDENSER	Bent / Punctured	1,385.50 FL	*1,385.50 FL
17	1		*CONDENSER SIDE GARNISH	O/S Torn	196.20 FL	*98.10 FL
18	1		*RADIATOR	Holder Cracked	1,662.30 FL	*1,662.30 FL
19	1		*RADIATOR FAN COWLING	Not Necessary	125.60 FL	*- FL
20	1		*FRONT FENDER O/S	Repair	745.10 FL	*- FL
21	1		*AIR DUCT	Torn	166.20 FL	*166.20 FL
22	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
23	1		*FRONT BUMPER LOWER SPOILER	Repair	680.00 FS	*- FS
24	1		*FRONT LICENCE PLATE	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	14,077.52	11,304.12
- List Item Discount on L Items 25.00/25.00% (S\$)	3,324.38	2,813.53
Total Parts (S\$)	10,753.14	8,490.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	60.00	60.00
3	TO REFILL AIR CON GAS	New	120.00	100.00
4	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	880.00	600.00
5	TO PUTTY & SPRAY PAINTING	New	1,200.00	800.00
Gross Labour Cost (S\$)			2,310.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >