

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21006968/BPA3Q2
Date: 20/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SMC5169U	Insured Vehicle No :	GBK771B
Date of Loss:	23/01/2021	Nature of Claim:	TP
		Claim No:	0451583168SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC5169U		
Make & Model:	MERCEDES-BENZ E200, 2.0 SE (A)	Engine No:	65492080226363
Reg. Date:	05/07/2018 (Man. Year: 2018)	Chassis No:	WDD2130132A464532
Colour:	Black	Odometer:	295100 km
Engine Capacity:	1950 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	General 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	General 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,865.53	5,897.90	6,967.63	54.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,550.00	1,300.00	2,250.00	63.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,415.53	7,197.90	9,217.63	56.15
Approved Total (Overridden) (S\$)		5,800.00		

(S\$)	16,415.53	5,800.00	10,615.53	64.67
+ GST 7.00/7.00% (S\$)	1,149.09	406.00	743.09	64.67
Nett Amount (S\$)	17,564.62	6,206.00	11,358.62	64.67
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		6,735.00		

INSPECTION

Date of Assignment: 23/06/2021

Date Inspected: 24/06/2021

Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)
 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
 Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	2,399.00 FL	*2,170.00 FL
2	1		*BOOTLID LOGO	Necessary	145.00 FL	*62.00 FL
3	1		*BOOTLID OUTER CHROME MOULDING	Cut	268.00 FL	*141.00 FL
4	1		*BOOTLID INNER LOCK	Not Damaged	483.60 FL	*- FL
5	1		*BOOTLID WEATHERSTRIP	Not Damaged	295.60 FL	*- FL
6	1		*REAR BUMPER	Cracked	2,044.00 FL	*1,740.00 FL
7	2		*REAR BUMPER RETAINER	Necessary	275.72 FL	*86.00 FL
8	1		*REAR BUMPER DIFFUSER	Cracked	583.36 FL	*485.00 FL
9	1		*REAR BUMPER DIFFUSER OUTER GARNISH	Cracked	168.00 FL	*168.00 FL
10	1		*REAR BUMPER REFLECTOR	N/S Broken	136.68 FL	*35.00 FL
11	1		*REAR BUMPER REINFORCEMENT	Not Damaged	751.33 FL	*- FL
12	1		*REAR BUMPER BRACKET	Broken	101.82 FL	*32.00 FL
13	4		*REAR BUMPER REVERSE SENSOR	Scratched (2 PCS ONLY)	980.00 FL	*360.00 FL
14	1		*REAR END PANEL	Not Damaged	1,752.30 FL	*- FL
15	1		*REAR END PANEL TOP GARNISH	Not Damaged	347.74 FL	*- FL
16	1		*REAR EXHAUST CHROME MOULDING	N/S Cut	316.00 FL	*158.00 FL
17	1		*TAIL LAMP	N/S Cut	1,788.00 FL	*894.00 FL
18	2		*TAIL LAMP LOWER BRACKET	Not Damaged	370.00 FL	*- FL
19	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
20	1		*BOOTLID SEALANT	Necessary	100.00 FS	*40.00 FS
21	1		*BOOTLID OUTER CHROME MOULDING CLIPS	Necessary	60.00 FS	*30.00 FS
22	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
23	1		*REAR BUMPER DIFFUSER CLIPS	Not Necessary	60.00 FS	*- FS
24	4		*REAR BUMPER REVERSE SENSOR SEAL	Necessary	260.00 FS	*60.00 FS
25	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
26	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
27	1		*TAILLAMP SEAL	N/S Necessary	120.00 FS	*40.00 FS
28	1		*REAR NUMBER PLATE W/CASING	Not Damaged	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,186.15	6,531.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,320.62	633.10
Total Parts (\$\$)	12,865.53	5,897.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R BOOTLID COMPONENT	New	150.00	80.00
2	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
3	DIAGNOSTIC RESET FAULT CODE	New	300.00	120.00
4	UPHOLSTERY	New	300.00	0.00
5	CHECK WIRING	New	100.00	40.00
6	PANEL BEATING	New	1,200.00	600.00
7	RUST PROOFING	New	200.00	0.00
8	SPRAY PAINTING	New	1,200.00	400.00
Gross Labour Cost (S\$)			3,550.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >