

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21006971/NRA3Q2
Date: 06/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210040873
Claimant Vehicle No :	SHC6951E	Insured Vehicle No :	SMZ5354E
Date of Loss:	22/06/2021	Nature of Claim:	TP
		Claim No:	4605262285SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC6951E	Engine No:	D4FDEH313480
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5639452
Reg. Date:	30/10/2015 (Man. Year: 2015)	Odometer:	549530 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Maxxis 4 mm	Rear Left Side:	Maxxis 4 mm
Front Right Side:	Maxxis 4 mm	Rear Right Side:	Maxxis 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	909.80	859.80	50.00	5.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	390.00	760.00	66.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,059.80	1,249.80	810.00	39.32
Approved Total (Overridden) (S\$)		1,000.00		

(S\$)	2,059.80	1,000.00	1,059.80	51.45
+ GST 7.00/7.00% (S\$)	144.19	70.00	74.19	51.45
Nett Amount (S\$)	2,203.99	1,070.00	1,133.99	51.45
+ Car Rental (4.0 x S\$42.76/day) (S\$)		171.04		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,243.04		

INSPECTION

Date of Assignment: 23/06/2021

Date Inspected: 24/06/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	696.00 FL	*696.00 FL
2	1		*REAR BUMPER LOWER COVER	Deformed	206.00 FL	*206.00 FL
3	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
4	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,000.00	950.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	90.20	90.20
Total Parts (\$\$)	909.80	859.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	50.00	0.00
2	TO DISMANTLE /REPLACE REVERSE SENSOT TO NEW BUMPER AND RESET TO THE SAME	New	120.00	30.00
3	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
4	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE SAME ETC	New	550.00	180.00
5	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER	New	250.00	180.00
Gross Labour Cost (S\$)			1,150.00	390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >