



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 3127C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE LID (N)	NOT NECESSARY	2,656.90	-
1	TAILGATE LID LOCK TOP (N)	NOT NECESSARY	162.20	-
1	TAILGATE LID LOCK STRIKER (N)	NOT NECESSARY	50.30	-
1	TAILGATE LID WEATHERSTRIP (N)	NOT NECESSARY	190.60	-
1	TAILGATE LID CENTRE LOGO BADGE (N)	NOT NECESSARY	64.60	-
1	TAILGATE LID QASHQAI BADGE (N)	NOT NECESSARY	64.60	-
1	REAR BUMPER (N) }	DEFORMED	831.00	796.70
1	REAR BUMPER CENTRE COVER (N) }		219.40	-
2	REAR BUMPER BRACKET @\$91.70 (N)	NOT NECESSARY	183.40	-
2	REAR BUMPER SIDE RETAINER @\$55.10 (N)	NOT NECESSARY	110.20	-
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	540.90	-
1	REAR BUMPER ABSORBER FOAM (N)	NOT NECESSARY	133.80	-
2	REAR BUMPER REFLECTOR @\$57.00 (N)	NOT NECESSARY	114.00	-
3	REAR BUMPER UPPER CLIP HOLDER @\$12.10 (N)	NOT NECESSARY	36.30	-
2	REAR BUMPER END SPLASHIELD COVER @\$45.60 (N)	NOT NECESSARY	91.20	-
1	REAR TOW COVER (N)	TORN	22.00	22.00
	LESS 10% DISCOUNT		-547.14	-81.87
			4,924.26	736.83
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN GLASS SEALANT (SN)	NOT NECESSARY	20.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	20.00	-
1	SET REAR BUMPER PARKING SENSOR (SN)	SHORTED	350.00	200.00
			390.00	200.00
<u>LABOUR</u>				
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMMINGS,GARNISH AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	120.00	-
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		80.00	40.00

Report Ref No. CS/AGI21006980/Uqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	140.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	250.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		800.00	500.00
			2,150.00	810.00
GRAND TOTAL			7,464.26	1,746.83
RECOMMENDED COST OF REPAIRS				1,746.83

Report Ref No. CS/AGI21006980/Uqf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.