

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21006981/AQCE2**Date:** 28/09/2021**REFERENCE**

Insured/Claimant:	AMELIA SANTOSA	Policy No:	1800149049
Date of Loss:	06/06/2021	Nature of Claim:	OD
		Claim No:	8555461861SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJE3277D</b>	Engine No:	CVK072177
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Chassis No:	WAUZZZF48KN000861
Reg. Date:	24/12/2018 (Man. Year: 2018)	Odometer:	13860 km
Colour:	Red		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$118,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,761.00	6,747.60	5,013.40	42.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,252.00	5,377.00	9,875.00	64.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>27,013.00</b>	<b>12,124.60</b>	<b>14,888.40</b>	<b>55.12</b>
<b>- Excess (\$\$)</b>	<b>1,100.00</b>	<b>1,100.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(\$\$)</b>	<b>25,913.00</b>	<b>11,024.60</b>	<b>14,888.40</b>	<b>57.46</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,813.91</b>	<b>771.72</b>	<b>1,042.19</b>	<b>57.46</b>
<b>Nett Amount (\$\$)</b>	<b>27,726.91</b>	<b>11,796.32</b>	<b>15,930.59</b>	<b>57.46</b>

**INSPECTION**

Date of Assignment:	24/06/2021		
Date Inspected:	23/06/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	9.0 days		

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SECTION PART - LEFT	Dented	4,052.00 FS	*3,241.60 FS
2	1		*REAR WINDSCREEN	Not Necessary	1,154.00 FS	*- FS
3	1		*REAR 1/4 GLASS - LH	Not Necessary	616.00 FS	*- FS
4	1		*PRIMER	Not Necessary	40.00 FS	*- FS
5	1		*REAR DOOR - LH	Dented	3,192.00 FS	*2,553.60 FS
6	1		*REAR DOOR OUTER SEAL - LH	Necessary	205.00 FS	*164.00 FS
7	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
8	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
9	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
10	1		*REAR DOOR SEALING STRIP	Not Necessary	17.00 FS	*- FS
11	1		*REAR ATTACHMENT PARTS	Not Necessary	860.00 FS	*- FS
12	1		*REAR DOOR CATCH - LH	Not Necessary	120.00 FS	*- FS
13	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
14	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
15	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
16	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
17	1		*METAL FILLER POWER	Necessary	280.00 FS	*280.00 FS
18	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
19	1		*SUNDRIES	Necessary	300.00 FS	*8.40 FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (\$\$)</b>	<b>11,761.00 6,747.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	0.00
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS	New	600.00	0.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND LHS 1/4 GLASS	New	400.00	0.00
4	TO CARRY OUT SEEPAGE TEST FOR RAER WINDSCREEN AND 1/4 GLASS	New	200.00	0.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	0.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY. ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	480.00
7	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WIDDOW DEVICES. INSPECT FOR DAMAGES	New	350.00	280.00
8	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	2,500.00
9	TO RESPRAY LHS REAR FENDER, LHS REAR DOOR, LHS SILL PANEL, ROOD CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANELLING	New	4,750.00	1,925.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>15,252.00</b>	<b>5,377.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >