

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21006982/AQCE2

Date: 29/09/2021

REFERENCE

Insured/Claimant:	AMELIA SANTOSA	Policy No:	1800149049		
Date of Loss:	17/06/2021	Nature of Claim:	OD	Claim No:	4807079446SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJE3277D	Engine No:	CVK072177
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Chassis No:	WAUZZZF48KN000861
Reg. Date:	24/12/2018 (Man. Year: 2018)	Odometer:	13860 km
Colour:	Red		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$118,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,986.00	1,914.96	4,071.04	68.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,502.00	1,602.00	900.00	35.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,488.00	3,516.96	4,971.04	58.57
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	7,938.00	2,966.96	4,971.04	62.62
+ GST 7.00/7.00% (S\$)	555.66	207.69	347.97	62.62
Nett Amount (S\$)	8,493.66	3,174.65	5,319.01	62.62

INSPECTION

Date of Assignment:	24/06/2021		
Date Inspected:	23/06/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,787.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	587.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	210.00 FS	*- FS
6	1		*FRONT RADIATOR GRILLE	Cracked	1,333.00 FS	*1,065.60 FS
7	1		*FRONT BUMPER REFORCEMENT ABSORBER	Cracked	124.00 FS	*99.20 FS
8	1		*FRONT BUMPER REFORCEMENT	Dented	845.00 FS	*675.60 FS
9	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
10	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
11	1		*AIR CONDITIONER STICKER	Not Necessary	8.00 FS	*- FS
12	1		*FRONT RADIATOR BRACKET	Not Necessary	137.00 FS	*- FS
13	2		*FRONT BUMPER BRACKET - LH / RH	Not Necessary	58.00 FS	*- FS
14	2		*FRONT BUMPER PARKING AID SENSOR - INNER / OUTER (NPA)	Not Necessary	0.00 FS	*- FS
15	4		*FRONT BUMPER PARKING AID SENSOR SEAL	Not Necessary	14.00 FS	*- FS
16	4		*FRONT RADIATOR AIR GUIDE	Not Necessary	80.00 FS	*- FS
17	1		*FRONT RADIATOR AIR GUIDE - UPPER	Not Necessary	16.00 FS	*- FS
18	1		*FRONT NUMBER PLATE	Dented	60.00 FS	*60.00 FS
19	1		*SUNDRIES	Necessary	300.00 FS	*14.56 FS
20	1		*OUTER TEMP. SENSOR BRACKET (Supplementary)	Not Necessary	19.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 5,986.00 1,914.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING LID	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY FRONT BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,502.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >