

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21006983/NRA3Q2
Date: 07/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800122897	
Claimant Vehicle No :	SG5098Z	Insured Vehicle No :	SMF4087M	
Date of Loss:	19/06/2021	Nature of Claim:	TP	Claim No: 7563831140SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SG5098Z		
Make & Model:	VOLVO B9TL, 9.4 D AUTO TURBO ABS (A)	Engine No:	D9195177
Reg. Date:	13/06/2016 (Man. Year: 2016)	Chassis No:	YV3S4P928GA177931
Colour:	Green	Odometer:	223929 km
Engine Capacity:	9364 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,707.10	3,341.39	365.71	9.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,400.00	3,700.00	2,700.00	42.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,107.10	7,041.39	3,065.71	30.33
+ GST 7.00/7.00% (S\$)	707.50	492.90	214.60	30.33

Nett Amount (S\$)	10,814.60	7,534.29	3,280.31	30.33
+ Loss of Use (6.0 x S\$350.00/day) (S\$)		2,100.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,636.29		

INSPECTION

Date of Assignment: 24/06/2021

Date Inspected: 24/06/2021

Estimated Period of Repair: 5.5 days

Inspected At:

Lexbuild International Pte Ltd
 LOYANG BUS DEPOT, 2 LOYANG WAY
 Singapore 508776

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EYE LID	Deformed	238.06 F	*238.06 FL
2	1		*FRONT RHS CORNER BUMPER	Deformed	754.86 F	*754.86 FL
3	1		*FRONT MID BUMPER	Cracked	740.85 F	*740.85 FL
4	1		*FRONT WINDSCREEN	Cracked	1,660.36 F	*1,660.36 FL
5	1		*SET WRIGHTBUS LOGO -CHROME LOGO	Necessary	262.97 F	*262.97 FL
6	1		*GO-AHEAD SINGAPORE STICKER	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,707.10	3,707.10
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	365.71
Total Parts (\$\$)	3,707.10	3,341.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SUPPLY SKILLED LABOUR TO REPLACE FRONT WINDSCREEN	New	1,760.00	880.00
2	SUPPLY SKILLED LABOUR TO:REPLACE FRONT RHS CORNER BUMPER,REPLACE FRONT MIDDLE BUMPER,REPLACE FRONT RHS EYELID REPLACE FRONT CHROME LOGO,REPAIR ,FIBERGLASS, GRINDING FRONT MIDDLE LOWER DOME	New	2,640.00	1,320.00
3	SUPPLY SKILLED PAINTER & PAINT MATERIAL TO PUTTY,GRINDING & SPRAYPAINT:REPLACE FRONT RHS CORNER BUMPER,REPLACE FRONT MIDDLE BUMPER,REPLACE FRONT RHS EYELID ,FRONT MIDDLE LOWER DOME	New	2,000.00	1,500.00
Gross Labour Cost (\$\$)			6,400.00	3,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >