

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21006986/AVCE2

**Date:** 29/09/2021

### REFERENCE

Insured/Claimant: FENG LIYUAN Policy No: 7210056892  
Date of Loss: 17/06/2021 Nature of Claim: OD Claim No: 2868452204SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNA2069T**  
Make & Model: AUDI Q3, 1.4 TFSI (A) Engine No: CZDC41552  
Reg. Date: 10/06/2021 (Man. Year: 2021) Chassis No: WAUZZZF38M1126574  
Colour: Green Odometer: 247 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: S\$175,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/65 R17 Rear Tyre Size: 215/65 R17  
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,238.00	3,146.48	7,091.52	69.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,452.00	2,422.00	14,030.00	85.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>26,690.00</b>	<b>5,568.48</b>	<b>21,121.52</b>	<b>79.14</b>
<b>- Excess (S\$)</b>	<b>800.00</b>	<b>800.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>25,890.00</b>	<b>4,768.48</b>	<b>21,121.52</b>	<b>81.58</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,812.30</b>	<b>333.79</b>	<b>1,478.51</b>	<b>81.58</b>
<b>Nett Amount (S\$)</b>	<b>27,702.30</b>	<b>5,102.27</b>	<b>22,600.03</b>	<b>81.58</b>

### INSPECTION

Date of Assignment: 24/06/2021  
Date Inspected: 23/06/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR PANEL - LH	Repair	3,388.00 FS	*- FS
2	1		*REAR SIDE WINDOW - LH	Not Necessary	614.00 FS	*- FS
3	1		*PRIMER	Not Necessary	20.00 FS	*- FS
4	1		*REAR DOOR - LH	Dented	2,909.00 FS	*2,327.20 FS
5	1		*REAR DOOR OUTER SEAL - LH	Necessary	135.00 FS	*108.00 FS
6	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	311.00 FS	*- FS
7	1		*REAR DOOR CATCH - LH	Not Necessary	120.00 FS	*- FS
8	1		*REAR DOOR LOWER COVER - LH	Cut	257.00 FS	*205.20 FS
9	1		*REAR DOOR HANDLE - LH	Cut	198.00 FS	*158.00 FS
10	1		*REAR DOOR HOUSING CAP - LH	Not Necessary	27.00 FS	*- FS
11	1		*REAR WHEEL SPOILER - LH	Not Necessary	39.00 FS	*- FS
12	1		*REAR WHEEL HOUSE LINER - LH	Not Necessary	241.00 FS	*- FS
13	1		*REAR WHEEL HOUSE LINER ATTACHMENT - LH / RH	Not Necessary	101.00 FS	*- FS
14	1		*REAR WHEEL ARCH COVER - LH / RH	N/S Cut	536.00 FS	*214.40 FS
15	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
16	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
17	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
18	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
19	1		*METAL FILLER POWER	Not Necessary	280.00 FS	*- FS
20	1		*SUNDRIES	Necessary	300.00 FS	*4.48 FS
21	1		*REAR DOOR MOUNTING BAR-LH (Supplementary)	Cracked	162.00 FS	*129.20 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 10,238.00 3,146.48**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND INSTALL REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	0.00
2	TO RENEW LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	0.00
3	TO INSTALL SOLAR FILM FOR LHS 1/4 GLASS	New	400.00	0.00
4	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS	New	200.00	0.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	0.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG, ETC	New	1,400.00	0.00
7	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,400.00	750.00
8	TO RESPRAY LHS REAR FENDER, LHS REAR DOOR, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANELLING	New	5,400.00	1,200.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
10	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	280.00
			<b>Gross Labour Cost (\$\$)</b>	<b>16,452.00</b>
				<b>2,422.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >