

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21006987/AVCE2

**Date:** 29/09/2021

### REFERENCE

Insured/Claimant:	LIM KAR HENG DENNIS	Policy No:	7210027627		
Date of Loss:	19/06/2021	Nature of Claim:	OD	Claim No:	4022088803SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV4898S		
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Engine No:	DEM025395
Reg. Date:	19/03/2021 (Man. Year: 2020)	Chassis No:	WAUZZZF45MN000903
Colour:	Black	Odometer:	7096 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$180,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,095.00	2,662.48	15,432.52	85.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,122.00	2,772.00	2,350.00	45.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,217.00</b>	<b>5,434.48</b>	<b>17,782.52</b>	<b>76.59</b>
<b>- Excess (S\$)</b>	<b>1,100.00</b>	<b>1,100.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>22,117.00</b>	<b>4,334.48</b>	<b>17,782.52</b>	<b>80.40</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,548.19</b>	<b>303.41</b>	<b>1,244.78</b>	<b>80.40</b>
<b>Nett Amount (S\$)</b>	<b>23,665.19</b>	<b>4,637.89</b>	<b>19,027.30</b>	<b>80.40</b>

### INSPECTION

Date of Assignment:	24/06/2021		
Date Inspected:	23/06/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,233.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	358.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	262.00 FS	*- FS
6	1		*FRONT RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	262.00 FS	*- FS
7	1		*FRONT RADIATOR GRILLE	Not Necessary	1,580.00 FS	*- FS
8	1		*FRONT BUMPER FOAM	Not Necessary	189.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER	Not Necessary	845.00 FS	*- FS
10	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
11	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
12	1		*A/C STICKER	Not Necessary	8.00 FS	*- FS
13	1		*FRONT LOCK CARRIER BRACKET	Not Necessary	137.00 FS	*- FS
14	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	58.00 FS	*- FS
15	1		*FRONT BONNET	Dented	3,246.00 FS	*2,596.80 FS
16	1		*FRONT BONNET ATTACHMENT PARTS	Not Necessary	412.00 FS	*- FS
17	1		*FRONT BONNET IMPACT PROTECTION - CENTER / LH / RH (3PCS)	Necessary	84.00 FS	*65.68 FS
18	1		*FRONT HEADLIGHT - RH	Not Necessary	7,685.00 FS	*- FS
19	3		*FRONT RADIATOR AIR GUIDE - RH / LH / UPPER	Not Necessary	76.00 FS	*- FS
20	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
21	1		*SUNDRIES	Not Necessary	192.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 18,095.00 2,662.48

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,122.00</b>	<b>2,772.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >