

TP EQ
Xiao Chen.

SMD9055H. 2018 Sept.

Kia Cerato. 1591 CC

KNAF1416MKS010020.

Rear Bumper	Distorted.	575.20 /
Rear Bumper Clips	N/A	30(SN) /
Rear Bumper Side Holder x 02	N/A	28 x 2 = 56. /
Rear Bumper lower Garnish	Distorted.	284.70 /
Rear Bumper lower Garnish Lower Cover		
Rear Bumper Lamp x 02	Cracked	163.2 x 2 = 326.40 /
Rear Bumper Lamp Cover x 02	Cracked	55.1 x 2 = 110.20 /
Rear Bumper Reinforcement	Cracked	287.50 /
Rear Bumper Reinforcement Bracket x 05	Damaged	18 x 5 = 90 /
Rear Bumper Reinforcement Stay x 02	Dented	82.6 x 2 = 165.20 /
Reverse Sensor x 04	2 pieces damaged	150 x 4 = 600 ^{3w.} /
Rear End Panel.	Dented	455.20. /
Rear End Panel Top Garnish.	Defaced	98.50 /
Rear End Panel Antenna Sensor	N/A	155.90. X-

SMD9055H.

Rear End Panel Top Garnish Clips. ^{Nec} 20(SN) ✓

Rear End Panel Sealant. ^{Nec} 60(SN) ✓

608.30.
 $608.3 \times 2 = 1216.60$

Taillamp x 02 LH cranked

1255 x

Bootlid ^{Repair}

Bootlid Lock

101.40 x

Bootlid Weatherstripe.

95.90 x.

Kia Logo

35.40 ✓

Crest Wording

39.40 ✓

Cycle and carriage Logo

45.10. ✓

Spere Tyre Panel Top Board.

260.90 ✓

Rear Exhaust Pipe.

758.40 x

Rear Exhaust Mounting

32.10 x

Reverse Sensor Wire Harness cranked 187.40 ✓

3925.40.

S.N: 110

3532.86

SMD 9055H.

Panel Beating

~~1200~~ 700

Spray Painting.

~~1200~~ 600

Wiring

~~50~~ 30

To remove reverse sensor

~~100~~ 50

To spray buff coat

~~150~~ 60

To remove upholstery.

~~150~~ 60

To transfer brotled fittings.

~~150~~ 60 1560

To remove exhaust pipe.

150 X

total: 5202.86

L/S: A.K.

05Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: