

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 6604Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BROKEN	698.10	458.60
2	REAR BUMPER RETAINER LH / RH	NECESSARY	139.00	139.00
2	REAR BUMPER IMPACT BRACKET LH / RH	NECESSARY	130.20	120.00
1	REAR END PANEL	DENTED	623.70	420.00
1	REAR END PANEL INNER GARNISH	BROKEN	263.80	150.02
1	REAR TAILGATE LOCK	NOT DAMAGED	466.50	-
1	REAR TAILGATE WEATHERSTRIP	TORN	359.10	198.00
2	REAR TAIL LAMP BRACKET LH / RH	NOT DAMAGED	132.20	-
1	KEYLESS SENSOR	BROKEN	295.00	102.20
	LESS 25% DISCOUNT		-776.90	-396.96
			2,330.70	1,190.86
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	30.00
1	REAR BUMPER PROTECTOR PLATE (SN)	DENTED	200.00	30.00
1	SET REAR REVERSE SENSOR (SN)	SHORT CIRCUIT	400.00	200.00
1	SET REAR END PANEL INNER GARNISH CLIP (SN)	NECESSARY	50.00	30.00
1	SET REAR TAILGATE INNER TRIM CLIP (SN)	NOT NECESSARY	60.00	-
			770.00	290.00
	<u>LABOUR</u>			
	CHECK REAR WIRING AND LIGHTING SYSTEM.	NOT NECESSARY	100.00	-
	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH.		200.00	30.00
	REMOVE AND RENEW REAR REVERSE SENSOR.		100.00	60.00
	PANEL BEATING ON REAR AFFECTED AREAS.		1,200.00	800.00
	SPRAY PAINTING ON REAR AFFECTED AREAS.		1,000.00	400.00
	APPLY ANTI RUST ON AFFECTED AREAS.		200.00	40.00
			2,800.00	1,330.00
	GRAND TOTAL		5,900.70	2,810.86

Report Ref No. CS/SMR21006989/Buf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,250.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMR21006989/Buf3e2

LIM TEOW GUAN

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator