

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 21.28818 Date: 26<sup>th</sup> July 2021

Our Ref: CS3/ASM21002081/Gvf3e2-1

## M/s Axa Insurance Pte Ltd

C/o Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLQ 9111Y INSURED VEHICLE: SLM 411L ACCIDENT DATE: 07/02/2021

We thank you for your instruction on 24/06/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLQ 9111Y from M/s C L Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles SLQ 9111Y and SLM 411L.
- c) Final Repair Bill of SLQ 9111Y from M/s Jementah Motor Works.
- d) Colour damaged vehicle photographs of SLQ 9111Y.

Pre-Repair Inspection Date: 18/02/2021 at M/s Jementah Motor Works, Blk 14 Defu Lane 10 #01-406, Singapore 539195.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SLQ 9111Y

Make & Model : Toyota Corolla Altis Classic 1.6 CVT

Year of Registration : 2015

Chassis Number : MR053REH104540929

Engine Capacity : 1598 cc

- 2. We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.