



24 Penshurst Place, Singapore 556440

Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783

Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Low Siew Hoon
C/o: Jementah Motor Works
Blk 14 Defu Lane 10
#01-406 Singapore 539195

Date : 3 March 2021
Our ref : JMW/02/2101/TP

Accident Date : 07 February 2021
Inspection Date : 16 February 2021
Repairer Name : Jementah Motor Works
Blk 14 Defu Lane 10
#01-406 Singapore 539195

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SLQ 9111 Y
Make / Model : Toyota Corolla Altis
Chassis No : MR053REH104540929
Engine No : 1ZR536525

Year / Capacity : 2015 / 1598 cc
Colour : White
Mileage : 177769

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	Yokohama	205/55 R16	5 mm	Sport
Front Offside	Yokohama	205/55 R16	5 mm	Sport
Rear Nearside	Yokohama	205/55 R16	5 mm	Sport
Rear Offside	Yokohama	205/55 R16	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the o/s portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 73 copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$9,900.00** on a contractual basis.

Under normal circumstances, the repair period would be about 9 (Nine) working days.

Vehicle Registration No.: SLQ 9111 Y

Our Ref No.: JMW/02/2101/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front o/s fender X SVC	Damage	\$ 908.70	\$ 908.70	
1	Front o/s fender inner shield SVC	Intact	\$ 209.10		
1	Front o/s fender "VVT-I" emblem ✓	Necessary	\$ 100.10	\$ 100.10	46
1	Front o/s door ✓	Damage	\$ 1,345.60	\$ 1,345.60	1143.4
1	Front o/s door lock X SVC	Damage	\$ 642.80	\$ 642.80	
1	Front o/s door rubber X SVC	Necessary	\$ 248.70	\$ 248.70	
1	Front o/s door side mirror X SVC	Damage	\$ 525.30	\$ 525.30	
1	O/s rocker panel X Repair	Damage	\$ 785.00	\$ 785.00	
1	Rear o/s door ✓	Damage	\$ 1,270.80	\$ 1,270.80	1121.1
1	Rear o/s door inner board X SVC	Damage	\$ 632.50	\$ 632.50	
1	Rear o/s door inner lock X SVC	Damage	\$ 548.30	\$ 548.30	
1	Rear o/s door rubber X SVC	Necessary	\$ 267.50	\$ 267.50	
1	Rear windscreen moulding X SVC	Necessary	\$ 156.80	\$ 156.80	
1	Rear o/s fender X Repair	Damage	\$ 1,120.70	\$ 1,120.70	
			\$ 8,761.90	\$ 8,552.80	2310.5
			<i>Less 25%</i>	<i>\$ 2,138.20</i>	
Total Cost - List Items			\$ 6,571.43	\$ 6,414.60	1732.88

SPECIAL NETT ITEMS

1	Front o/s tyre (Depreciation) X SVC	Damage	\$ 450.00	\$ 225.00	
1	Front o/s wheel rim ✓	Damage	\$ 800.00	\$ 800.00	400
1	Front o/s door black tape ✓	Necessary	\$ 120.00	\$ 120.00	60
1	Rear o/s door black tape ✓	Necessary	\$ 120.00	\$ 120.00	60
1	Rear windscreen sealant X SVC	Necessary	\$ 80.00	\$ 50.00	
1	Rear o/s tyre (Depreciation) X SVC	Damage	\$ 450.00	\$ 225.00	
1	Rear o/s wheel rim ✓	Damage	\$ 800.00	\$ 800.00	400
Total Cost - Special Nett items			\$ 2,820.00	\$ 2,340.00	920

Total cost of parts

\$ 9,391.43	\$ 8,754.60
--------------------	--------------------

Vehicle Registration No.: SLQ 9111 Y

Our Ref No.: JMW/02/2101/TP

S/No	Description	Repairer's Estimate	Revised Amount
Total cost of parts c/f		\$ 9,391.43	\$ 8,754.60

LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00	×
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 120.00	×
3	To conduct wheel alignment.	\$ 150.00	\$ 120.00	60
4	To remove and refit rear windscreen glass.	\$ 180.00	\$ 120.00	×
5	To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door.	\$ 700.00	\$ 240.00	60
6	To apply undercoating on repaired and replaced panel.	\$ 200.00	\$ 150.00	60
7	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,800.00	\$ 1,500.00	600
8	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,600.00	\$ 1,320.00	1000

GRAND TOTAL

\$ 14,251.43	\$ 12,374.60	1780
---------------------	---------------------	-------------

4432.88

-20%: 3550

5 Days

Vehicle Registration No.: SLQ 9111 Y

Our Ref No.: JMW/02/2101/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 9,900.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser