

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL		Ref: CS3/AGI21007003/Vvf3e2		
(BUDGET DIRECT INSURANCE) 190		Date: 06/07/2021		
CLEMENCEAU AVENUE #03-01 SINGAPORE				
SHOPPING CENTRESINGAPORE 239924		Code: AGI		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SDM 9449P	Veh. Inspected	SMV 1029S	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10010589/KY	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	24/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE 1.5G	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	GK82102542	Colour	GREY	
Odometer	22422 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	20/06/2021	Inspection Date	24/06/2021	
Survey held at	LKT GROUP PTE LTD 3006 UBI ROAD 1 #01-384 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408700			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		