#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21007011/T1TCE2

15/09/2021 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

Policy No: DMB1SNW00000022101 (Singapore) Pte. Ltd.

**Claimant Vehicle** 

Insured Vehicle CB6620A 442CK

No:

No:

Claim SNM21D201639/C02/TANKL Date of Loss: 22/03/2021 Nature of Claim: TP

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

442CK Reg No:

ELECTRIC BICYCLE SUV-7, (A) Make & Model: Engine No: HIDDEN

Reg. Date: (Man. Year: ) Chassis No: 577911907021415

Colour: Black Odometer: 0 km

**Engine Capacity:** 0 сс N/A Market Value/New Car Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 12 1/2 X 2 1/4 Rear Tyre Size: 12 1/2 X 2 1/4 Front Left Side: CST 5 mm Rear Left Side: CST 5 mm Front Right Side: Rear Right Side: 0 mm  $0 \, \text{mm}$ 

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

**INSPECTION** 

Date of Assignment: 07/09/2021

BLK 194B BUKIT BATOK WEST AVENUE 6 29/06/2021 Inspected At: Date Inspected:

Singapore 652194

Estimated Period of Repair: 0.0 days

MOHD TAUFIKH BIN HAMID DENISE TAY KWEE CHENG Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

#### TOTAL LOSS ASPECT

DEPRECIATION VALUE \$809.10

### **REPAIR DETAILS**

#### Reference

Part Source: (Last Synchronised: 13 Sep 2021)

Parts: N/A ELECTRIC BICYCLE SUV-7 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for 442CK)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

There are no new parts selected.

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >