9/10/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/GRB21007013/KBA3Q2

Date:

10/09/2021

REFERENCE

Date of Loss:

Handling Insurer: India International Insurance Pte Ltd Policy No:

D21MFL0000447

Claimant Vehicle No:

SHD9988A 24/06/2021 Insured Vehicle No:

Nature of Claim:

SLM6972U TP

Claim No: MFL2021D0002751

2ZR2G76599

76188 km

JTDKB3FUX03091243

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD9988A

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)

03/08/2020 (Man. Year: 2020) Reg. Date:

Colour: Metallic Pearl White/Red

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Footbrake (Serviceable):

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable): Yes

Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: Rear Left Side:

195/65 R15 Sailun 9 mm

Front Left Side: Sailun 9 mm Front Right Side: Sailun 9 mm

Rear Right Side:

Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,126.82	280.88	5,845.94	95.42
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,840.00	420.00	4,420.00	91.32
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	10,966.82	700.88	10,265.94	93.61
	+ GST 7.00/7.00% (S\$)	767.68	49.06	718.62	93.61

Nett Amount (S\$)	11,734.50	749.94	10,984.56	93.61
+ Loss of U	se (3.0 x S\$40.00/day) (S\$)	120.00		
+ Car Ren	tal (3.0 x S\$96.30/day) (S\$)	288.90		
	+ Doc/Search Fee (S\$)	7.45		
	Nett Liability (S\$)	1,166.29		
	Global Sum Settlement (S\$)	1,150.00		

INSPECTION

Date of Assignment: 24/06/2021

Trans-cab Auto Services Pte Ltd Date Inspected: Inspected At: No 2 Ang Mo Kio Street 63 25/06/2021

Singapore 569111

Estimated Period of Repair: 1.5 days

Adjuster: KENNETH KONG Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Sep 2021)

TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue: Merimen Singapore 1.0) Parts: 144

(Price-denominated Standard List) Labour: Repairer's

(Unsubmitted, no print-code for SHD9988A) **Print Code:**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

lo. Qty P	Part No.	Particulars	Condition	Repairer's	Amount
1		*COVER ,REAR BUMPER	Repair	485.60 FL	*- FL
. 1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	332.70 FL	*- FL
1		*GUARD ,REAR BUMPER ,CENTER	Dented	374.50 FL	*374.51 FL
. 1		*COVER ,REAR BUMPER LOWER	Serviceable	22.00 FL	*- FL
5 1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	132.60 FL	*- FL
5 1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	132.60 FL	*- FL
1		*REFLECTOR ASSY REFLEX ,LH	Serviceable	39.00 FL	*- FL
3 1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	651.00 FL	*- FL
1		*COVER ,DECK TRIM ,REAR	Serviceable	126.70 FL	*- FL
0 1		*COVER ,FLOOR UNDER NO.2 (RH)	Serviceable	241.90 FL	*- FL
1 1		*COVER ,FLOOR UNDER NO.1 (LH)	Serviceable	175.10 FL	*- FL
2 1		*COVER ,REAR FLOOR (CTR)	Serviceable	229.90 FL	*- FL
3 1		*PANEL SUB-ASSY ,BACK DOOR	Repair	1,147.80 FL	*- FL
4 1		*GARNISH SUB-ASSY ,BACK DOOR OUTSIDE	Serviceable	913.60 FL	*- FL
5 1		*STAY ASSY ,BACK DOOR ,LH	Serviceable	242.50 FL	*- FL
6 1		*STAY ASSY ,BACK DOOR ,RH	Serviceable	242.50 FL	*- FL
7 1		*HINGE ASSY ,BACK DOOR ,LH	Repair	61.00 FL	*- FL
8 1		*HINGE ASSY ,BACK DOOR ,RH	Repair	61.00 FL	*- FL
9 1		*ORNAMENT SUB-ASSY ,BACK DOOR	Not Necessary	47.90 FL	*- FL
20 1		*PLATE ,LUGGAGE COMPARTMENT DOOR NAME NO.2	Not Necessary	54.60 FL	*- FL
1 1		*PLATE ,BACK DOOR NAME, NO.1	Not Necessary	54.60 FL	*- FL
2 1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
.3 1		*SET REAR BUMPER CLIP	Not Necessary	85.00 FS	*- FS
.4 1		*BUMPER CENTRE GUARD CLIP	Not Necessary	80.00 FS	*- FS
25 1		*REAR BUMPER PROTECTOR	Serviceable	180.00 FS	*- FS
26 1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS
27 1		*BOOT STICKER TRANSCAB	Not Necessary	100.00 FS	*- FS

No.	Qty Pa	art No.	Particulars	Condition	Repairer's	Amount
28	1		*BOOT STICKER 65553333	Not Necessary	100.00 FS	*-FS
29	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*-FS
30	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
31	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS
F=Fr	anchise part	rt. S=SpcNett. I	L=ListItemDisc.	· -		
				Sub Total (S\$)	7,569.10	374.51
				- List Item Discount on L Items 25.00/25.00% (S\$)	1,442.28	93.63
				Total Parts (S\$)	6,126.82	280.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO RUST -PROOFING AND APPALY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,600.00	200.00
TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	220.00
TO REMOVE AND REFIT REAR BIG & SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
Gross La		4,840.00	420.00
	TO RUST -PROOFING AND APPALY UNDERCOAT OF THE AFFECTED AREAS TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER , TO ENABLE REPAIR PANEL BEATING , KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS , ADJUST AND REALIGN THE SAME TO TRANSFER OF REAR END PANEL FITTINGS , ATTACHMENT TO FACILITATE BODYWORK REPAIR PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION TO REMOVE AND REFIT REAR BIG & SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR TO REINSTALL REAR BUMPER PARKING SENSOR TO CHECK ELECTRICAL LIGHTING CONCERNED	TO RUST -PROOFING AND APPALY UNDERCOAT OF THE AFFECTED AREAS TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER, TO ENABLE REPAIR PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ADJUST AND REALIGN THE SAME TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT TO FACILITATE BODYWORK REPAIR New PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION New TO REMOVE AND REFIT REAR BIG & SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR New TO REINSTALL REAR BUMPER PARKING SENSOR	TO RUST -PROOFING AND APPALY UNDERCOAT OF THE AFFECTED AREAS TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS ADJUST AND REALIGN THE SAME TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT TO FACILITATE BODYWORK REPAIR New 380.00 PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION TO REMOVE AND REFIT REAR BIG & SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR New 300.00 TO REINSTALL REAR BUMPER PARKING SENSOR New 170.00 TO CHECK ELECTRICAL LIGHTING CONCERNED

Report was unsubmitted during this print-out.

< END OF ESTIMATES >