

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21007026/EQF3E2

Date: 30/07/2021

REFERENCE

Insured/Claimant:	PHILIP CHEONG SANG LEE	Policy No:	1800127207	
Date of Loss:	25/06/2021	Nature of Claim:	OD	Claim No: 9770496990SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF4546E	Engine No:	G4FGJH709397
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5019989
Reg. Date:	13/11/2018 (Man. Year: 2018)	Odometer:	51556 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$73,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R16	Rear Tyre Size:	225/40Z R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,778.00	5,443.40	3,334.60	37.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,950.00	4,570.00	1,380.00	23.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,728.00	10,013.40	4,714.60	32.01
+ GST 7.00/7.00% (S\$)	1,030.96	700.94	330.02	32.01
Nett Amount (S\$)	15,758.96	10,714.34	5,044.62	32.01

INSPECTION

Date of Assignment:	25/06/2021	
Date Inspected:	25/06/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	8.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*NEW K3 2020 RUNWAY RED CR5	Broken	1,721.00 FS	*1,721.00 FS
3	1		*COVER-RR BUMPER	Broken	651.00 F	*651.00 FL
4	1		*COVER-RR BUMPER LWR	Broken	241.00 F	*241.00 FL
5	1		*COVER-RR BUMPER UNDER, LH	Not Necessary	33.00 F	*- FL
6	1		*COVER-RR BUMPER FOG LAMP, RH	Not Necessary	88.00 F	*- FL
7	1		*LAMP ASSY-SIDE T/SIGNAL, RH	Not Necessary	181.00 F	*- FL
8	1		*EXTN WIRING ASSY-BWS	Not Necessary	207.00 F	*- FL
9	1		*BRACKET-RR BEAM UPR MTG, RH	Not Necessary	9.00 F	*- FL
10	1		*BEAM-RR BUMPER	Broken	318.00 F	*318.00 FL
11	1		*BRACKET-RR BEAM LWR, CTR	Not Necessary	6.00 F	*- FL
12	1		*BRACKET-RR BEAM LWR MTG	Not Necessary	6.00 F	*- FL
13	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	46.00 F	*- FL
14	1		*STAY-RR BUMPER RH	Bent	65.00 F	*65.00 FL
15	1		*BRACKET-ASSY RR BPR SIDE UPR, R	Not Necessary	31.00 F	*- FL
16	1		*ULTRASONIC SENSOR ASSY-BWS	Damaged / Broken	163.00 F	*163.00 FL
17	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 F	*1,297.00 FL
18	1		*PANEL ASSY-BACK	Dented	324.00 F	*324.00 FL
19	1		*TRIM ASSY-TRUNK LID	Not Necessary	202.00 F	*- FL
20	1		*W/STRIP-TRUNK LID OPNG	Crushed	100.00 F	*100.00 FL
21	1		*LATCH ASSY-TRUNK LID	Not Necessary	112.00 F	*- FL
22	1		*LOGO ASSY-KIA SUB	Necessary	32.00 F	*32.00 FL
23	1		*EMBLEM-CERATO	Necessary	28.00 F	*28.00 FL
24	1		*TRIM ASSY-RR TRANSVERSE	Broken	41.00 F	*41.00 FL
25	1		*LAMP ASSY-REAR COMB OUTSIDE, RH	Cut	675.00 F	*675.00 FL
26	1		*LAMP ASSY-REAR COMB INSIDE, RH	Cut	608.00 F	*608.00 FL
27	1		*LAMP ASSY-CENTER GARNISH	Not Necessary	690.00 F	*- FL
28	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	41.00 F	*- FL
29	1		*MUFFLER ASSY-REAR	Not Necessary	757.00 F	*- FL
30	1		*STAY-RR BUMPER LH (Supplementary)	Bent	65.00 F	*65.00 FL
31	10		*CLIP (Supplementary)	Necessary	20.00 F	*20.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,778.00	6,369.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	925.60
Total Parts (\$\$)	8,778.00	5,443.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR BUMPER, REAR AIRDAM, BOOTLID, REAR END PANEL. REPAIR LAMP HOUSING LH & RH	New	2,000.00	1,600.00
2	REMOVE & INSTALL REAR AIRDAM	New	100.00	80.00
3	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
4	SPRAY PAINT FOR REAR AIR DAM, REAR BUMPER, REAR END PANEL, BOOTLID, REAR LAMP HOUSING RH LH, REAR FENDER RH	New	3,360.00	2,400.00
5	REMOVE & INSTALL REAR COMPARTMENT TRIMS	New	200.00	200.00
6	APPLY SEALANT FOR ACCIDENT PORTION	New	80.00	80.00
7	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (\$)			5,950.00	4,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >