

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21007027/R1VF3E2

Date: 15/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900083590
Claimant Vehicle No :	SBS3850U	Insured Vehicle No :	SJN1551C
Date of Loss:	23/06/2021	Nature of Claim:	TP
		Claim No:	1118672076SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS3850U	Engine No:	D9193200
Make & Model:	VOLVO B9TL, 9.4 D AUTO TURBO ABS (A)	Chassis No:	YV3S4P924EA168818
Reg. Date:	08/10/2014 (Man. Year: 2014)	Odometer:	494567 km
Colour:	Multi-colour		
Engine Capacity:	9364 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70R22.5	Rear Tyre Size:	275/70R22.5(D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8/8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	320.28	320.28	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	478.40	478.40	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	798.68	798.68	0.00	0.00
+ GST 7.00/7.00% (S\$)	55.91	55.91	0.00	0.00
Nett Amount (S\$)	854.59	854.59	0.00	0.00

INSPECTION

Date of Assignment:	25/06/2021		
Date Inspected:	25/06/2021	Inspected At:	SBS Transit Ltd (Bukit Batok) 550 Bukit Batok Street 23 Singapore 659519
Estimated Period of Repair:	1.0 days		

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S CORNER BUMPER	Cracked	214.40 FS	*214.40 FS
2	1		*N/S DEFLECTOR	Cracked	64.00 FS	*64.00 FS
3	1		*PAINT C6000 VOLVO PURPLE	Necessary	21.12 FS	*21.12 FS
4	1		*PAINT C600 VOLVO WHIE	Necessary	20.76 FS	*20.76 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					320.28	320.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE / REPLACE / REPAIR DAMAGED PARTS BY WORKSHOP	New	478.40	478.40
2	TO REMOVE / REPLACE / REPAIR DAMAGED PARTS BY CONTRACTOR (NPA)	New	0.00	0.00
3	TO REMOVE / REPLACE / REPAIR DAMAGED ADVERTISEMENT PANEL (NPA)	New	0.00	0.00
4	TOWING COST (NPA)	New	0.00	-
Gross Labour Cost (S\$)			478.40	478.40

Report was unsubmitted during this print-out.

< END OF ESTIMATES >