

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21007028/EYA3Q2**Date:** 09/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100485158
<b>Claimant Vehicle No :</b>	GBK1532T	<b>Insured Vehicle No :</b>	SGM6933S
Date of Loss:	18/06/2021	Nature of Claim:	TP
		Claim No:	9089082908SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBK1532T</b>		
Make & Model:	NISSAN NV350, 2.5 PANEL VAN 5AT 5DR (A)	Engine No:	YD25056141B
Reg. Date:	29/01/2020 (Man. Year: 2019)	Chassis No:	JN1MC2E26Z0031499
Colour:	White	Odometer:	22384 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,773.62	1,281.81	491.81	27.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	450.00	950.00	67.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,173.62</b>	<b>1,731.81</b>	<b>1,441.81</b>	<b>45.43</b>
<b>+ GST 7.00/7.00% (S\$)</b>	222.15	121.23	100.92	45.43
<b>Nett Amount (S\$)</b>	<b>3,395.77</b>	<b>1,853.04</b>	<b>1,542.73</b>	<b>45.43</b>
<b>+ Loss of Use (3.0 x S\$70.00/day) (S\$)</b>		210.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,065.04</b>		

**INSPECTION**

Date of Assignment:	25/06/2021	Efficient Motor & Engineering Works Pte Ltd (HQ) 56 Loyang Way #06-07, Loyang Enterprise Building Singapore 508775
Date Inspected:	23/07/2021 Inspected At:	
Estimated Period of Repair:	3.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** Ezlyna

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	571.90 FL	*571.90 FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Broken	147.00 FL	*147.00 FL
3	1		*FRONT FOG LAMP GARNISH RH	Not Necessary	104.70 FL	*- FL
4	1		*HEADLAMP ASSY RH	Cut	672.00 FL	*672.00 FL
5	1		*FRONT STEP PANEL GARNISH RH	Not Necessary	235.00 FL	*- FL
6	1		*FRONT WHEEL HUB CAP LH	Not Necessary	151.20 FL	*- FL
7	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
8	1		*COMPANY REGISTRATION STICKER	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,961.80	1,420.90
- List Item Discount on L Items 10.00/10.00% (\$)	188.18	139.09
Total Parts (\$)	1,773.62	1,281.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEAT & STRAIGHTEN DAMAGED PANELS .TO REMOVE & REPLACE PARTS	New	600.00	200.00
2	TO APPLY ANTI RUST COAT AND TUFF KOTE AFFECTED AREAS	New	50.00	20.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING HARNESS	New	50.00	30.00
4	TO SPRAY PAINTING FRONT BUMPER & FRONT LEFT DOOR & AFFECTED PARTS	New	700.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,400.00</b>	<b>450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >