9/20/21, 10:03 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21007029/ATCN2

20/09/2021 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNW00161052004

Claimant Vehicle

SLW5432R

No:

Insured Vehicle SLH9739J

No: Date of Loss:

07/06/2021

Nature of Claim: TP

Claim SNM21D203224/C02/CSC No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLW5432R Reg No:

MITSUBISHI ASTRA HB, 3.0 D FB70BBA20549 (M) Make & Model: Engine No: 4B11XR1943

Reg. Date: 21/02/2018 (Man. Year: 2017) Chassis No: JMFXTGA2WJZ009085

Colour: Silver Odometer: 49451 km

Engine Capacity: 1998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 225/55R18 Rear Tyre Size: 225/55R18 Front Left Side: Rear Left Side: Bridgestone 6 mm Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,632.90	1,084.50	1,548.40	58.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	630.00	900.00	58.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,162.90	1,714.50	2,448.40	58.81
+ GST 7.00/7.00% (S\$)	291.40	120.02	171.38	58.81
Nett Amount (S\$)	4.454.30	1,834.52	2,619.78	58.81

INSPECTION

Date of Assignment: 17/09/2021

Progressive Car Care Pte Ltd (HQ) Date Inspected: 28/06/2021 Inspected At: Blk 3022A Ubi Road 1, #01-45/46

Singapore 408716

Estimated Period of Repair: 3.0 days

DENISE TAY KWEE CHENG Adjuster: **ADRIAN LING** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 20 Sep 2021)

Parts: N/A MITSUBISHI ASTRA HB 3.0 D FB70BBA20549 (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLW5432R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,000.00 FL	*1,000.00 FL
2	2		*REAR BUMPER SIDE HOLDER-LH & RH	Not Necessary	56.00 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	210.00 FL	*- FL
5	1		*REAR BUMPER TOW COVER	Not Necessary	22.00 FL	*- FL
6	2		*REAR BUMPER REFLECTOR-LH & RH	Not Necessary	220.00 FL	*- FL
7	1		*REAR EXHAUST	Not Necessary	950.00 FL	*- FL
8	1		*REAR TAILGATE ASX LOGO	Necessary	50.00 FL	*50.00 FL
9	1		*REAR TAILGATE MIVEC LOGO	Necessary	50.00 FL	*50.00 FL
10	1		*REAR TAILGATE MITSUBISHI EMBLEM	Necessary	60.00 FL	*60.00 FL
11	1		*REAR BUMPER CENTRE BRACKET	Not Necessary	18.00 FL	*- FL
12	1		*SET REAR BUMPER SENSOR	Not Necessary	220.00 FS	*- FS
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	2,901.00	1,205.00
			- List Item Discount on L	. Items 10.00/10.00% (S\$)	268.10	120.50
				Total Parts (S\$)	2,632.90	1,084.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO KNOCK OUT DENTS,REMOVE,REPLACE ACCIDENT PAI	RTS New	700.00	200.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	600.00	400.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE, REFIX REAR GARNISH TO FACILITATE REPAIR	R New	80.00	0.00
5	REMOVE,REPLACE REAR EXHAUST & CHROME	New	100.00	0.00
	Gro	oss Labour Cost (S\$)	1,530.00	630.00
	Report was unsubmitted o	during this print-out.		

< END OF ESTIMATES >