

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21007030/NPA3Q2**Date:** 09/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070035431
<b>Claimant Vehicle No :</b>	SHC8869Y	<b>Insured Vehicle No :</b>	SMS9250G
Date of Loss:	23/06/2021	Nature of Claim:	TP
		Claim No:	9954298651SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHC8869Y</b>		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4DFDU565017
Reg. Date:	24/03/2016 (Man. Year: 2015)	Chassis No:	KMHLB41UMGU086800
Colour:	Blue	Odometer:	690938 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,965.60	2,399.36	566.24	19.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	840.00	420.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,225.60</b>	<b>3,239.36</b>	<b>986.24</b>	<b>23.34</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,500.00</b>		
<b>(S\$)</b>	4,225.60	2,500.00	1,725.60	40.84
<b>+ GST 7.00/7.00% (S\$)</b>	295.79	175.00	120.79	40.84
<b>Nett Amount (S\$)</b>	<b>4,521.39</b>	<b>2,675.00</b>	<b>1,846.39</b>	<b>40.84</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b>		150.00		
<b>+ Car Rental (3.0 x S\$110.67/day) (S\$)</b>		332.01		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,159.01</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,100.00</b>		

INSPECTION

Date of Assignment:	25/06/2021	
Date Inspected:	25/06/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

**Adjuster:** Muhammad Nazril Bin Abdullah**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Deformed	1,052.20 FL	*1,052.20 FL
2	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*FRT BUMPER BRACKET TOP LH	Serviceable	44.80 FL	*- FL
4	1		*FRT FENDER LH	Repair	663.00 FL	*- FL
5	1		*HEADLAMP LH	Scratched	1,800.00 FL	*1,800.00 FL
6	1		*FRT FENDER ADVERTISEMENT LOGO LH	Necessary	100.00 FS	*100.00 FS
					<b>Sub Total (\$\$)</b>	<b>3,682.00 2,974.20</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>716.40 574.84</b>
					<b>Total Parts (\$\$)</b>	<b>2,965.60 2,399.36</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	600.00	560.00
2	SPRAY PAINTING CHARGE	New	600.00	250.00
3	WIRING CHARGE	New	60.00	30.00
<b>Gross Labour Cost (\$)</b>			<b>1,260.00</b>	<b>840.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >