

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007031/NTCQ2**Date:** 21/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00004132000

Claimant Vehicle No : SLJ3584S **Insured Vehicle No :** SME9018K

Date of Loss: 23/06/2021 Nature of Claim: TP Claim No: SNM21D203545/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ3584S**

Make & Model: HONDA HR-V, 1.5 DX CVT (A) Engine No: L15B4531088

Reg. Date: 07/12/2016 (Man. Year: 2016) Chassis No: JHMRU1810GX201088

Colour: White Odometer: 76653 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,392.76	6,121.60	6,271.16	50.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,500.00	2,180.00	6,320.00	74.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,892.76	8,301.60	12,591.16	60.27
Approved Total (Overridden) (S\$)		6,650.00		
(S\$)	20,892.76	6,650.00	14,242.76	68.17
+ GST 7.00/7.00% (S\$)	1,462.49	465.50	996.99	68.17
Nett Amount (S\$)	22,355.25	7,115.50	15,239.75	68.17

INSPECTION

Date of Assignment: 28/06/2021

Date Inspected: 25/06/2021 Inspected At: AP Automotive Services Pte Ltd (HQ)
Blk 9006 Tampines Street 93, #01-202
Singapore 528840

Estimated Period of Repair: 5.0 days

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Apr 2022)	
Parts:	N/A	HONDA HR-V 1.5 DX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ3584S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	972.00 FL	*800.00 FL
2	4		*TAILGATE WINDSCREEN MOULDING	Necessary	152.00 FL	*152.00 FL
3	2		*TAILGATE LAMP L+R	Cracked	542.00 FL	*542.00 FL
4	1		*TAILGATE HANDLE SWITCH	Serviceable	145.00 FL	*- FL
5	1		*TAILGATE LOGO +HONDA	Necessary	95.00 FL	*50.00 FL
6	1		*TAILGATE EMBLEM -HR-V	Necessary	88.00 FL	*50.00 FL
7	1		*TAILGATE EMBLEM -I-VTEC	Necessary	80.00 FL	*50.00 FL
8	1		*TAILGATE LOCK	Deformed	155.00 FL	*155.00 FL
9	1		*TAILGATE LOCK CATCH	Deformed	90.00 FL	*90.00 FL
10	2		*TAILGATE HINGE L+R	Serviceable	172.00 FL	*- FL
11	2		*TAILGATE DAMPER L+R	Serviceable	516.00 FL	*- FL
12	1		*TAILGATE INNER TRIM	Cracked	183.00 FL	*183.00 FL
13	1		*TAILGATE WEATHERSTRIP	Torn	110.00 FL	*110.00 FL
14	2		*TAIL LAMP L+R	Cracked	882.00 FL	*700.00 FL
15	2		*TAIL LAMP PANEL L+R	Serviceable	274.00 FL	*- FL
16	1		*REAR SIDE BUMPER L+R	N/S Cracked / O/S Serviceable	330.00 FL	*165.00 FL
17	2		*REAR SIDE BUMPER RETAINER L+R	Serviceable	42.00 FL	*- FL
18	1		*REAR BUMPER	Deformed	829.00 FL	*600.00 FL
19	2		*REAR BUMPER REFLECTOR L+R	Cracked	164.00 FL	*164.00 FL
20	2		*REAR BUMPER RETAINER L+R	Serviceable	160.00 FL	*- FL
21	1		*REAR BUMPER UNDERCOVER	Serviceable	129.00 FL	*- FL
22	2		*REAR FENDER L+R	Serviceable	1,350.00 FL	*- FL
23	2		*REAR FENDER INNER TRIM LOWER L+R	Cracked	298.00 FL	*298.00 FL
24	1		*REAR FENDER AIRVENT LH	Serviceable	93.00 FL	*- FL
25	2		*REAR FENDER COWLING L+R	Serviceable	246.00 FL	*- FL
26	1		*REAR WHEEL ARC PROTECTOR L+R	N/S Deformed / O/S Serviceable	396.00 FL	*198.00 FL
27	1		*END PANEL	Dented	415.00 FL	*415.00 FL
28	1		*END PANEL TOP GARNISH	Cracked	135.00 FL	*135.00 FL
29	1		*FLOOR PANEL	Dented	858.00 FL	*700.00 FL
30	1		*FLOOR PANEL TOP BOARD	Deformed	502.00 FL	*250.00 FL
31	1		*FLOOR PANEL ACCESSORIES BOX	Deformed	252.00 FL	*150.00 FL
32	1		*FLOOR PANEL TOOLS SPONGE	Deformed	165.00 FL	*120.00 FL
33	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*80.00 FS
34	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	100.00 FS	*50.00 FS
35	1		*REVERSE CAMERA	Serviceable	750.00 FS	*- FS
36	1		*SET TAIL LAMP CLIPS	Necessary	50.00 FS	*30.00 FS
37	2		*TAIL LAMP PANEL SEALANT	Not Necessary	200.00 FS	*- FS
38	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
39	1		*SET REAR BUMPER REVERSE SENSOR	Deformed	300.00 FS	*200.00 FS
40	1		*SET REAR SIDE BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
41	1		*REAR FENDER INNER TRIM CLIPS	Necessary	200.00 FS	*30.00 FS
42	1		*SET REAR FENDER COWLING CLIPS	Serviceable	200.00 FS	*- FS
43	1		*SET REAR WHEEL ARC PROTECTOR CLIPS	Necessary	200.00 FS	*30.00 FS
44	1		*END PANEL SEALANT	Necessary	200.00 FS	*60.00 FS
45	1		*FLOOR PANEL SEALANT	Necessary	300.00 FS	*80.00 FS
46	1		*EXHAUST PIPE	Dented	896.85 FL	*650.00 FL

Report was unsubmitted during this print-out.

4/21/22, 2:56 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	2		*SET EXHAUST MOUNTING	Necessary	150.20 FL	*100.00 FL
48	1		*EXHAUST HEAT SHIELD	Serviceable	98.90 FL	*- FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	14,785.95 7,487.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	2,393.19 1,365.40
					Total Parts (\$\$)	12,392.76 6,121.60
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,600.00	900.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,800.00	900.00
3	TO RNR REAR WINDSCREEN	New	400.00	120.00
4	TO RNR REAR EXHAUST	New	250.00	0.00
5	TO CHECK WIRING AND TAIL LAMP FUNCTION }	New	150.00	50.00
6	TO CHECK WIRING AND TAILGATE LAMP FUNCTION }	New	150.00	0.00
7	TO RNR REAR INNER TRIMS AND UPHOLSTERY	New	400.00	0.00
8	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	0.00
9	TO RNR UNDERCARRIAGE	New	250.00	0.00
10	TO CHECK WATER LEAK	New	150.00	0.00
11	TO RNR FUEL TANK	New	250.00	0.00
12	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
13	TO RNR REAR TAILGATE MECHANISM	New	400.00	50.00
14	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
15	TO PERFORM RUST PROOFING	New	400.00	80.00
16	TO RNR REAR EXHAUST	New	300.00	50.00
Gross Labour Cost (\$\$)			8,500.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >