



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2107426

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 27/10/2021
Reference CC6/CTI21007035/Ura3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GBG 368D
Insured Veh. YL 6210L
Claim No. SNM21D203560/LKKDS
Policy No. DMCVSNW00013602106
Accident Date 25/06/2021
Inspection Date 25/06/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21007035/Ura3q2 Date: 27/10/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YL 6210L	Veh. Inspected	GBG 368D	
Policy No.	DMCVSNW00013602106	Coverage (\$)	0.00	
Claim No.	SNM21D203560/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	25/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KDY2318026964	Colour	SILVER	
Odometer	141644 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/70 R15	KAPSEN	6 mm	
L/H Front Tyre	195/70 R15	KAPSEN	6 mm	
R/H Rear Tyre	155 R13 (D)	GREEN MAX	6/6 mm	
L/H Rear Tyre	155 R13 (D)	GREEN MAX	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/06/2021	Inspection Date	25/06/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 368D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	DENTED /BENT	1,655.10	1,498.85
2	TAILGATE LOCK LATCHS @\$245.00	O/S BENT	490.00	119.30
2	TAILGATE 'L' LOWER PANELS @\$115.00	O/S BENT	230.00	68.50
2	TAILGATE 'L' LOWER PANEL RUBBERS @\$105.00	O/S TORN	210.00	65.00
1	TAILGATE LOWER MEMBER	BENT / TWISTED	655.10	605.10
2	TAILGATE LOWER REFLECTORS @\$99.10	O/S CRACKED	198.20	99.10
1	DROPSIDE GATE O/S	DENTED / BENT	2,455.10	1,866.10
1	DROPSIDE GATE LOWER MEMBER O/S	DENTED / BUCKLED	985.20	877.00
2	TAILLAMPS @\$296.90	O/S CRACKED	593.80	285.50
2	TAILLAMP BRACKETS @\$105.00	O/S BENT	210.00	105.00
2	TAILLAMP LOWER REFLECTORS @\$65.00	O/S CRACKED	130.00	65.00
1	REAR EXHAUST	NOT NECESSARY	488.20	-
1	DYNA STICKER	NECESSARY	68.00	68.00
1	REAR SPARE TYRE CHAIN & BRACKET	NOT NECESSARY	398.20	-
1	REAR LICENCE PLATE BRACKET	NOT NECESSARY	198.50	-
1	FRONT PANEL	DENTED / BENT	1,615.10	1,566.10
1	FRONT PANEL CENTRE BLACK GARNISH	GRAZED / CRACKED	366.50	266.20
2	FRONT CORNER PANELS @\$205.00	TO REPAIR SEE LABOUR	410.00	-
1	FRONT CORNER PANEL TOP BLACK GARNISH N/S	GRAZED / CRACKED	155.10	115.00
1	FRONT DYNA STICKER	NOT FITTED	85.00	-
1	FRONT WINDSCREEN RUBBER	NECESSARY	211.10	211.10
1	FRONT GRILLE	CRACKED	675.10	615.10
1	FRONT GRILLE LOGO	NECESSARY	105.00	102.00
2	HEADLAMPS @\$905.10	CRACKED	1,810.20	1,566.20
1	FRONT BUMPER	DENTED	488.20	488.20
1	FRONT FOG LAMP N/S	CRACKED	455.20	255.10
1	FRONT CROSS MEMBER	TO REPAIR SEE LABOUR	655.50	-
1	FRONT CABIN CROSS MEMBER	NOT NECESSARY	850.10	-

Report Ref No. CC6/CTI21007035/Ura3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR CON BLOWER	CRACKED	1,005.30	1,005.30
1	AIR CON HEATER UNIT	CRACKED	1,650.00	1,615.10
1	AIR CON CONDENSER	TO REPAIR SEE LABOUR	1,220.20	-
1	FRONT DOOR VIEW MIRROR BRACKET N/S	BENT/ CRACKED	485.20	391.00
1	FRONT DOOR N/S	TO REPAIR SEE LABOUR	1,715.10	-
1	FRONT CABIN REAR PILLAR O/S	TO REPAIR SEE LABOUR	655.10	-
1	DASHBOARD	NOT NECESSARY	845.20	-
	LESS 25% DISCOUNT		-	-3,479.71
			24,423.60	10,439.14
	<u>SPECIAL NETT ITEMS</u>			
1	REAR LICENCE PLATE (SN)	NOT NECESSARY	20.00	-
1	SET 13 PAX & 70KM/H STICKER (SN)	NECESSARY	30.00	20.00
1	REAR STEP PANEL (SN)	TO REPAIR SEE LABOUR	180.00	-
1	1500KG STICKER (SN)	NECESSARY	80.00	30.00
1	SET REAR REVERSE SENSOR (SN)	NOT FITTED	280.00	-
1	TAILGATE ALUMINIUM PLATE (SN)	BENT	680.00	400.00
1	DROPSIDE GATE ALUMINIUM N/S (SN)	TO REPAIR SEE LABOUR	880.00	-
1	SET ALUMINIUM RIVET (SN)	NECESSARY	80.00	60.00
1	FRONT LICENCE PLATE (SN)	NOT NECESSARY	20.00	-
			2,250.00	510.00
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR .	NOT NECESSARY	80.00	-
	TO DISMANTLE & REFIX REAR EXHAUST .	NOT NECESSARY	80.00	-
	TO REFILL AIR CON GAS .		100.00	100.00
	TO LIFT UP REAR CARGO DECK FOR REPAIR CHASSIS.	NOT NECESSARY	680.00	-
	TO DISMANTLE & REFIX FRONT WINDSCREEN .		150.00	80.00
	TO DISMANTLE & REFIX FRONT DASHBOARD .		300.00	200.00
	TO DISMANTLE & REPLACING AIR CON BLOWER .		100.00	100.00

Report Ref No. CC6/CTI21007035/Ura3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY RUST PROOFING .		100.00	100.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT CORNER PANELS,FRONT CROSS MEMBER,AIR CON CONDENSER,FRONT DOOR N/S ,FRONT CABIN REAR PILLAR O/S,REAR STEP PANEL AND DROPSIDE GATE ALUMINIUM N/S.		2,800.00	1,800.00
	TO PUTTY & SPRAY PAINTING.		2,400.00	1,680.00
			6,840.00	4,090.00
GRAND TOTAL			33,513.60	15,039.14
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				12,000.00

Report Ref No. CC6/CT121007035/Ura3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 368D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 368D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 368D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

