

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT       |   |  |                     |                         |  |
|------------------------------------|---|--|---------------------|-------------------------|--|
|                                    | LONPAC INSURAN  | NCE BHD  | Ref:                | CS3/LPC21007040/Buf3e2  |  |
|                                    | 300 BEACH ROAD<br>#17-04/07 THE CO  | NCOURSESINGAPORE 199555                              | Date:               | 28/07/2021              |  |
|                                    |   |  | Code:               | LPC2                    |  |
| 1.                                 | Policy Particulars :- (THIRD PARTY CLAIM)   |  |                     |                         |  |
|                                    | Insured Veh.  | SMR 276Y   | Veh. Inspected      | SLM 8051P               |  |
|                                    | Policy No.  |  | Coverage (\$)       | 0.00                    |  |
|                                    | Claim No.   | 21/21/21/VP05/024691                                 | Excess (\$)         | 0.00                    |  |
|                                    | Assign From   | ONG LI LI  | Assign Date         | 25/06/2021              |  |
| 2. Vehicle Particulars & Condition |   |  |                     |                         |  |
|                                    | Make & Model  | HONDA STREAM 1.8X                                    | c.c                 | 1799                    |  |
|                                    | Engine No.  | HIDDEN   | Year of Reg.        | 2009                    |  |
|                                    | Chassis No.   | RN61089412   | Colour              | BLACK                   |  |
|                                    | Odometer  | 385601 KM  | Steering            | IN ORDER                |  |
|                                    | Brakes  | IN ORDER   | Modification        | SPORTS RIM              |  |
|                                    | General   | POOR   |                     |                         |  |
| 3. Conditions of Tyres             |   |  |                     |                         |  |
|                                    |   | Size   | Make                | Balance                 |  |
|                                    | R/H Front Tyre  | 215/45 R17   | WEST LAKE           | 5 mm                    |  |
|                                    | L/H Front Tyre  | 215/45 R17   | WEST LAKE           | 5 mm                    |  |
|                                    | R/H Rear Tyre   | 215/45 R17   | WEST LAKE           | 5 mm                    |  |
|                                    | L/H Rear Tyre   | 215/45 R17   | WEST LAKE           | 5 mm                    |  |
| 4. Description of Damages          |   |  |                     |                         |  |
|                                    | THE VEHICLE SUS<br>PORTION.   | STAINED DAMAGES AT THE FRO                           |                     |                         |  |
| 5.                                 | General Information   |  |                     |                         |  |
|                                    | Accident Date   | 23/06/2021   | Inspect Date / Time | 28/06/2021 ( 11:24 AM ) |  |
|                                    | Survey held at  | MJE MOTOR  |                     |                         |  |
|                                    |   | BLK 7 SIN MING IND EST SEC C #01-96 SINGAPORE 575642 |                     |                         |  |
| 5a.                                | 5a. Remarks   |  |                     |                         |  |
|                                    | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |  |                     |                         |  |

Report Ref No. CS3/LPC21007040/Buf3e2

Inspected By

LIM TEOW GUAN

K.K.LAU CPT(RET)

**Automotive Assessor** 

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser