

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD INV No. AC2105584

3 ANSON ROAD #16-00 INV Date 10/08/2021 SPRINGLEAF TOWER Reference CC6/CTI21

SPRINGLEAF TOWER

SINGAPORE 079909

Reference CC6/CTI21007041/Kea3q2

Code CTI

#### PROFESSIONAL SERVICE FEE

Vehicle No. SKQ 2682Z

Insured Veh. GBH 2557G

Claim No. SNM21D203579/C02

Policy No. DMCVSNW00034332101

Accident Date 22/06/2021

Inspection Date 24/06/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

**LKM** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

CHINA TAIPING INSURANCE (S) PTE LTD         Ref: CC6/CTI21007           3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909         Date: 10/08/2021           Code: CTI           1. Policy Particulars :- THIRD PARTY CLAIM           Insured Veh.         GBH 2557G         Veh. Inspected         SKQ 2682Z           Policy No.         DMCVSNW00034332101         Coverage (\$)         0.00           Claim No.         SNM21D203579/C02         Excess (\$)         0.00           Assign From         Assign Date         24/06/2021	7041/Kea3q2						
Code: CTI							
1.         Policy Particulars :- THIRD PARTY CLAIM           Insured Veh.         GBH 2557G         Veh. Inspected         SKQ 2682Z           Policy No.         DMCVSNW00034332101         Coverage (\$)         0.00           Claim No.         SNM21D203579/C02         Excess (\$)         0.00							
Insured Veh.   GBH 2557G   Veh. Inspected   SKQ 2682Z							
Policy No.         DMCVSNW00034332101         Coverage (\$)         0.00           Claim No.         SNM21D203579/C02         Excess (\$)         0.00							
Claim No. SNM21D203579/C02 Excess (\$) 0.00							
Assign From Assign Date 24/06/2021							
, ,							
2. Vehicle Particulars & Condition							
Make & Model TOYOTA WISH (A) c.c 1797							
Engine No. HIDDEN Year of Reg. 2014	2014						
Chassis No. ZGE206016689 Colour METALLIC SIL	LVER						
Odometer 137221 KM Steering IN ORDER							
Brakes IN ORDER Modification SPORTS RIM	SPORTS RIM						
General GOOD							
3. Conditions of Tyres							
Size Make Balance							
R/H Front Tyre         195/65 R15         MICHELIN         8 mm							
L/H Front Tyre 195/65 R15 MICHELIN 8 mm							
R/H Rear Tyre 195/65 R15 MICHELIN 8 mm							
L/H Rear Tyre 195/65 R15 MICHELIN 8 mm							
4. Description of Damages							
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.							
DAMAGES SEE DETAILS.							
5. General Information							
Accident Date 22/06/2021 Inspection Date 24/06/2021							
Survey held at ALAN'S UNITED AUTO PTE LTD							
BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642	#01-76						
5a. Remarks							
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b. Estimate Days of Repair	Estimate Days of Repair						
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days							



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 2682Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR N/S FENDER	BENT	838.60	838.60
1	REAR N/S QUARTER GLASS MOULDING	NECESSARY	178.40	178.40
1	REAR N/S MUDFLAP	SERVICEABLE	73.90	-
1	REAR BUMPER FASCIA	CRACKED	491.90	491.90
1	REAR N/S BUMPER SIDE RETAINER	DISTORTED	89.90	89.90
1	REAR N/S TAILLAMP LOWER BRACKET	SERVICEABLE	58.20	-
	LESS 25% DISCOUNT		-432.73	-399.70
			1,298.17	1,199.10
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	50.00
1	REAR N/S QUARTER GLASS SEALANT (SN)	NECESSARY	60.00	40.00
			110.00	90.00
	<u>LABOUR</u>			
	TO REMOVE & REFIX REAR N/S QUARTER GLASS .		100.00	60.00
	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET.		180.00	100.00
	TO APPLY UNDERSEALING .		80.00	30.00
	TO PUTTY AND SPRAY REPLACED PARTS.		600.00	420.00
	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS.		700.00	600.00
			1,660.00	1,210.00
	GRAND TOTAL		3,068.17	2,499.10

RECOMMENDED COST OF LUMP SUM REPAIRS		2,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC6/CTI21007041/Kea3q2

KONG SENG CHEONG

**Licensed Appraiser** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SKQ 2682Z

#### **INSPECTION**















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SKQ 2682Z

**RE-INSPECTION** 



