

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG121007044/ATF3N2**Date:** 14/03/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SMW9682Y **Insured Vehicle No :** GBJ8511M

Date of Loss: 23/06/2021 Nature of Claim: TP Claim No: CDMCG21001161

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMW9682Y**

Make & Model: MERCEDES-BENZ CLA200, 1.6 (R18) (A) Engine No: 27091030350179

Reg. Date: 21/03/2014 (Man. Year: 2014) Chassis No: WDD1173432N073727

Colour: Grey Odometer: 115279 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,311.70	5,229.50	5,082.20	49.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	1,590.00	1,990.00	55.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,891.70	6,819.50	7,072.20	50.91
Approved Total (Overridden) (S\$)		5,200.00		
(S\$)	13,891.70	5,200.00	8,691.70	62.57
+ GST 7.00/7.00% (S\$)	972.42	364.00	608.42	62.57
Nett Amount (S\$)	14,864.12	5,564.00	9,300.12	62.57

INSPECTION

Date of Assignment: 28/06/2021

Date Inspected: 28/06/2021 Inspected At: Stk Auto (s) Pte Ltd (HQ)
8 kaki bukit ave4, #03-21
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2022)
Parts:	143	MERCEDES-BENZ CLA200 1.6 (R18) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW9682Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Repair	1,600.00 FL	*- FL
2	1	*BONNET HINGE	Not Necessary	125.00 FL	*- FL
3	1	*HEADLAMP RH	Cracked	2,850.00 FL	*2,579.00 FL
4	1	*HEADLAMP CONTROL MODULE RH (VOLTAGE CONVERTER)	Not Necessary	990.00 FL	*- FL
5	1	*HEADLAMP CONTROL MODULE RH (XENON)	Not Necessary	365.00 FL	*- FL
6	1	*FRT BUMPER FASCIA	Deformed	1,800.00 FL	*1,421.00 FL
7	1	*FRT BUMPER FOG LAMP COVER RH	Not Necessary	67.00 FL	*- FL
8	1	*FRT BUMPER FOG LAMP COVER BASED RH	Not Necessary	90.00 FL	*- FL
9	1	*FRT BUMPER LOWER GRILL RH	Deformed	210.00 FL	*82.00 FL
10	1	*FRT BUMPER LICENSE PLATE GARNISH	Not Necessary	125.00 FL	*- FL
11	1	*FRT BUMPER HEADLAMP NOZZLE COVER RH	Not Necessary	63.00 FL	*- FL
12	1	*FRT BUMPER RETAINER RH	Damaged	165.00 FL	*85.00 FL
13	1	*FRT FENDER RH	Buckled	700.00 FL	*700.00 FL
14	1	*FRONT WHEEL HOUSING RH	Not Necessary	240.00 FL	*- FL
15	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	395.00 FL	*- FL
16	1	*FRONT REINFORCEMENT BRACKET RH	Not Necessary	185.00 FL	*- FL
17	1	*FRT SUPPORT PANEL	Damaged	830.00 FL	*830.00 FL
18	1	*FRT INNER AIR DUCT RH	Not Necessary	55.00 FL	*- FL
19	1	*FRT INNER BRACKET RH	Cracked	58.00 FL	*58.00 FL
20	10	*FRT TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
21	12	*FRT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
22	2	*FRT BUMPER SENSOR RH	Not Necessary	380.00 FS	*- FS
23	2	*FRT BUMPER SENSOR ORING	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,403.00	5,805.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,091.30	575.50
Total Parts (\$\$)	10,311.70	5,229.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	300.00	30.00
2	FRT PORTION COMPARTMENT RIGHT	New	250.00	0.00
3	LABOUR FOR REMOVE & REFIX DAMAGED PARTS,STRAIGHTEN PANEL AND ALIGN ALL PARTS	New	1,200.00	750.00
4	TO RESPRAY PAINTING	New	1,050.00	500.00
5	TUFF KOTE	New	150.00	0.00
6	TO RENEW AIR CON CONDENSER VACUUM & TOP UP GAS	New	180.00	80.00
7	TO RENEW RADIATOR & TOP UP COOLANT	New	150.00	80.00
8	TO PERFORM DIAGNOSTIC TEST	New	300.00	150.00
Gross Labour Cost (\$\$)			3,580.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >