

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4
#03-21 S415875

STK AUTO(S) PTE LTD
Email:stkautosg@gmail.com
Contact Person: TAN GUOHUA
HP: 91237949/63860669

Date: 6/25/2021
To: ERGO INSURANCE PTE LTD
Attn: Moto Claim Department

Denise

ESTIMATED REPAIR COST DETAILS

Owner: ZHENG CHENG XIONG
Vehicle Number: SMW9682Y
Make & Model: MERCEDES CLA200
Accident Date: 6/23/2021

C/N	LIST ITEM	QTY	AMOUNT
1	BONNET <i>Repair</i>	1	\$ 1600 +
2	BONNET HINGE <i>Not m</i>	1	\$ 125 +
3	HEADLAMP RH <i>Cracked</i>	1	\$ 2850 <i>2579</i>
4	HEADLAMP CONTROL MODULE RH (VOLTAGE CONVERTER) <i>Not m</i>	1	\$ 990 +
5	HEADLAMP CONTROL MODULE RH (XENON) <i>Not m</i>	1	\$ 365 +
6	FRT BUMPER FASCIA <i>Delnd</i>	1	\$ 1800 <i>1421</i>
7	FRT BUMPER FOG LAMP COVER RH <i>Delnd Not m</i>	1	\$ 67 +
8	FRT BUMPER FOG LAMP COVER BASED RH <i>Not m</i>	1	\$ 90 +
9	FRT BUMPER LOWER GRILL RH <i>Delnd</i>	1	\$ 210 <i>82</i>
10	FRT BUMPER LICENSE PLATE GARNISH <i>Not m</i>	1	\$ 125 +
11	FRT BUMPER HEADLAMP NOZZLE COVER RH <i>Not m</i>	1	\$ 63 +
12	FRT BUMPER RETAINER RH <i>Delnd</i>	1	\$ 165 <i>85</i>
13	FRT FENDER RH <i>Breached</i>	1	\$ 700 ✓
14	FRONT WHEEL HOUSING RH	1	\$ 240 +
15	FRONT BUMPER REINFORCEMENT <i>Not m</i>	1	\$ 395 +
16	FRONT REINFORCEMENT BRACKET RH <i>Not m</i>	1	\$ 185 +
17	FRT SUPPORT PANEL <i>Not m Damaged</i>	1	\$ 830 <i>less 10%: 5179.50</i>
18	FRT INNER AIR DUCT RH <i>Not m</i>	1	\$ 55 +
19	FRT INNER BRACKET RH <i>Not m Cracked</i>	1	\$ 58 ✓
Sub Total			\$ 10913
LESS 10% Disc			\$ 109.1
Total			\$ 10803.9

SPECIAL NETT ITEM

1	FRT TOP GARNISH CLIPS <i>Not m</i>	10	\$ 30 +
2	FRT BUMPER CLIPS <i>Not m</i>	12	\$ 60 <i>30</i>
3	FRT BUMPER SENSOR RH <i>Not m</i>	2	\$ 380 +
4	FRT BUMPER SENSOR ORING <i>Not m</i>	2	\$ 20 ✓
Total			\$ 490

50

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4
#03-21 S415875

STK AUTO(S) PTE LTD
Email:stkautosg@gmail.com
Contact Person: TAN GUOHUA
HP: 91237949/63860669

Date: 6/25/2021
To: ERGO INSURANCE PTE LTD
Attn: Moto Claim Department

ESTIMATED REPAIR COST DETAILS

Owner: ZHENG CHENG XIONG
Vehicle Number: SMW9682Y
Make & Model: MERCEDES CLA200
Accident Date: 6/23/2021

C/N	LABOUR COST	AMOUNT
1	TO CHECK WIRING SYSTEM	\$ 300 30.
2	FRT PORTION COMPAREMENT RIGHT	\$ 250 x.
3	LABOUR FOR REMOVE & REFIX DAMAGE PARTS, STRAIGHTEN PANEL AND ALIGN ALL PARTS	\$ 1200 750
4	TO RESPRAY PAINTING	\$ 1050 500.
5	TUFF KOTE	\$ 150 x
Total		\$ 2950

Grand Total \$ 2970

C/N	SUPPLEMENTARY LABOUR COST	AMOUNT
1	To renew air con condenser vacuum & top us gas	\$ 180 80
2	To renew radiator & top up coolant	\$ 150 80.
3	To perform diagnostic test	\$ 300 150.
Total		\$ 630

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L.
L/s 28/06/21.

total: 6508.50

L/s: S21C.
06 Days

14293.90