

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD	Ref	CS3/ASM21007051/Euce2	
	8 SHENTON WAY TOWERSINGAPO	-	Date	e: 15/07/2021	
	ATTN: ANG RICHA	ARD	Cod	le: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SH 6608R	Veh. Inspected	FX 361K	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S1M03CNO	Excess (\$)	0.00	
	Assign From	ANG RICHARD	Assign Date	25/06/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	HONDA CB400	c.c	399	
	Engine No.	HIDDEN	Year of Reg.	2006	
	Chassis No.	JH2NC39935M100309	Colour	YELLOW	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	120/60Z R17	PIRELLI	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	160/60Z R17	PIRELLI	5 mm	
	L/H Rear Tyre			mm	
4.	4. Description of Damages				
	THE VEHICLE SU	STAINED DAMAGES AT THE FRO			
5.	General Information				
	Accident Date	24/06/2021	Inspect Date / Time	28/06/2021 (10:30 AM)	
	Survey held at	20 BUKIT BATOK CRESCENT #	01-19 ENTERPRISE C	ENTRE	
	Repairer	Repairer PRIMERO RACING			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/ASM21007051/Euce2

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser