



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2107176

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 18/10/2021
Reference CC6/CTI21007052/Ues3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GBF 4114Z
Insured Veh. GX 5752X
Claim No. SNM21D203587C02
Policy No. DMCVSNW00056522000
Accident Date 23/06/2021
Inspection Date 25/06/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21007052/Ues3q2	
			Date: 18/10/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GX 5752X	Veh. Inspected	GBF 4114Z	
Policy No.	DMCVSNW00056522000	Coverage (\$)	0.00	
Claim No.	SNM21D203587C02	Excess (\$)	0.00	
Assign From		Assign Date	25/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KDY2318025631	Colour	SILVER	
Odometer	95330 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	165 R13 (D)	TIANFU	6/6 mm	
L/H Rear Tyre	165 R13 (D)	TIANFU	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/06/2021	Inspection Date	25/06/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 4114Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	DENTED / BENT	1,845.10	1,645.10
1	TAILGATE DYNA STICKER	NECESSARY	45.50	45.50
1	TAILGATE LOWER MMEBER	BENT	745.10	565.10
1	TAILGATE LOCK LATCH O/S	SERVICEABLE	119.30	-
2	TAILLAMPS @\$285.30	CRACKED	570.60	570.60
2	TAILLAMP PANELS @\$119.30	TO REPAIR SEE LABOUR	238.60	-
1	TAILGATE LOWER 'L' PANEL N/S	TO REPAIR SEE LABOUR	68.50	-
1	TAILGATE LOWER 'L' PANEL RUBBER N/S	NOT NECESSARY	62.30	-
1	REAR EXHAUST PIPE	NOT NECESSARY	585.20	-
1	REAR EXHAUST PIPE MOUNTING	NOT NECESSARY	112.00	-
1	REAR CENTRE CROSS MEMBER	NOT NECESSARY	845.20	-
1	REAR SPARE TYRE CHAIN & BRACKET	DAMAGED	392.50	392.50
1	REAR SPARE TYRE 'L' BRACKET	NOT NECESSARY	85.00	-
1	REAR TAILGATE REFLECTOR O/S	CRACKED	99.10	99.10
1	REAR TAILLAMP LOWER REFLECTOR O/S	NOT NECESSARY	88.50	-
1	REAR STEP BRACKET	TO REPAIR SEE LABOUR	119.50	-
	LESS 25% DISCOUNT		-	-829.48
			6,022.00	2,488.42
<u>SPECIAL NETT ITEMS</u>				
1	TAILGATE 70KM/HR & 8 PAX STICKER (SN)	NECESSARY	20.00	20.00
1	SET REAR REVERSE SENSOR (SN)	SERVICEABLE	680.00	-
1	REAR LICENCE PLATE (SN)	CRACKED	40.00	40.00
1	REAR 1500KG STICKER (SN)	NOT NECESSARY	80.00	-
1	TAILGATE INNER ALUMINIUM PLATE (SN)	TO REPAIR SEE LABOUR	680.00	-
1	SET TAILGATE INNER ALUMINIUM PLATE RIVET (SN)	NECESSARY	80.00	50.00
			1,580.00	110.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO CHECK WIRING.		80.00	20.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO SPRAY RUST PROOFING.		120.00	60.00
	TO DISMANTLE & REPLACING REAR EXHAUST.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF TAILLAMP PANELS, TAILGATE LOWER 'L' PANEL N/S, REAR STEP BRACKET AND TAILGATE INNER ALUMINIUM PLATE.		1,000.00	850.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	800.00
			2,880.00	1,780.00
	GRAND TOTAL		10,482.00	4,378.42
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,500.00

Report Ref No. CC6/CTI21007052/Ues3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 4114Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 4114Z

RE-INSPECTION

