

ASS. REC. BY: Marcus

REF:

CC6/CT121007052/Us3

ASSIGNMENT

From: Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

N/S	O/S

\$48k.

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

Vehicle: IN / OUT

Veh No:

G8F41142

Yr Regn:

13/10/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CM/

Make:

Toyota Dyna

c.c 2982

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

95-330

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KDY2318025631

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195 R15 Yokohama
R: 165 R13 Tientu

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

23/6/21

D.O.I.

25/6/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/7/21

have G.A
2/5 @ 3500 confirmed with Alan

Date/Time, File Pass to?

: Preli. Report
 : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1)

Date/Time, File Return to?

2)

Add Fee:

: Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

HKW Asher

not Authorized
Rak
25/6/21
1/58 3500
Hdgs.

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6
01-48 S'PORE 417883

VEHICLE NO: GBF 4114Z

1PC	TAILGATE	DD/Bent	1645.10	\$1,845.10	—
1PC	TAILGATE DYNA STICKER	nek		\$45.50	—
1PC	TAILGATE LOWER MEMBER	Bent		\$745.10	—
1PC	TAILGATE LOCK LATCH O/S	sek	565.10	\$119.30	X
2PCS	TAILLAMPS @\$ 285.30	cre		\$570.60	—
2PCS	TAILLAMP PANELS @ \$119.30	r		\$238.60	X
1PC	TAILGATE LOWER 'L' PANEL N/S	r		\$68.50	X
1PC	TAILGATE LOWER 'L' PANEL RUBBER N/S	n		\$62.30	X
1PC	REAR EXHAUST PIPE	n		\$585.20	X
1PC	REAR EXHAUST PIPE MONTING	na		\$112.00	X
1PC	REAR CENTRE CROSS MEMBER	n		\$845.20	X
1PC	REAR SPARE TYRE CHAIN & BRACKET	Damaged		\$392.50	—
1PC	REAR SPARE TYRE 'L' BRACKET	n		\$85.00	X
1PC	REAR TAILGATE REFLECTOR O/S	cre		\$99.10	—
1PC	REAR TAILLAMP LOWER REFLECTOR O/S	n		\$88.50	X
1PC	REAR STEP BRACKET	r		\$119.50	X
	S.NETT			\$6,022.00	
1PC	TAILGATE 70KM/hr & 8PAX STICKER	nek		\$20.00	✓
1SET	REAR REVERSE SENSOR	sek		\$680.00	X
1PC	REAR LICENCE PLATE	cre		\$40.00	✓
1PC	REAR 1500kg STICKER	na		\$80.00	X
1PC	TAILGATE INNER ALUMINIUM PLATE	r		\$680.00	X
1SET	TAILGATE INNER ALUMINIUM PLATE RIVET	nek		\$80.00	50
	TO CHECK WIRING			\$80.00	20
	TO DISMANTLE & REPLACING REVERSE SENSOR			\$80.00	50
	TO SPRAY RUST PROOFING			\$120.00	60
	TO DISMANTLE & REPLACING REAR EXHAUST			\$100.00	X
	LABOUR FOR PANEL BEATING & REPLACING PARTS			\$1,000.00	850
	TO PUTTY & SPRAY PAINTING			\$1,500.00	800

(252)

LKK Auto Consultants to TOTALify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 3317.9
252
248.42
4378.42