

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III21007054/UPA3Q2

Date:

16/07/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D20MFL0003256_01

Claimant Vehicle No : GBH9285U**Insured Vehicle No :**

PC1020E

Date of Loss: 25/06/2021

Nature of Claim:

TP

Claim No:

MFL2021D0002702

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBH9285U**

Make & Model: TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M)

Engine No:

1KD2075632

Reg. Date: 18/03/2011 (Man. Year: 2011)

Chassis No:

JTFAT35Y90K201449

Colour: Silver

Odometer:

170682 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size:

155 R12 (D)

Front Left Side: Yokohama 6 mm

Rear Left Side:

Dunlop 6/6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Dunlop 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,916.55	1,975.50	4,941.05	71.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,530.00	1,410.00	47.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,856.55	3,505.50	6,351.05	64.43
Approved Total (Overridden) (S\$)		2,800.00		

Nett Amount (S\$)		9,856.55	2,800.00	7,056.55	71.59
Global Sum Settlement (S\$)			0.00		

INSPECTION

Date of Assignment:	25/06/2021		
Date Inspected:	28/06/2021	Inspected At:	Profi Automotive (KB) 10 KAKI BUKIT ROAD 2, #01-05 FIRST EAST CENTRE Singapore 417868
Estimated Period of Repair:	4.0 days		

Adjuster:	MARCUS CHUA	Manager:	CHEW HSIAO TONG
------------------	-------------	-----------------	-----------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Jul 2021)	
Parts:	N/A	TOYOTA DYNA 150 MANUAL 3SEATER 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH9285U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT CORNER PANEL RH	Dented	205.40 FL	*205.40 FL
2	1		*FRONT CORNER PANEL TO GARNISH RH	Missing / Broken	122.70 FL	*122.70 FL
3	1		*FRONT HEADLAMP RH	Broken	646.10 FL	*646.10 FL
4	1		*FRONT GRILLE	Cracked	593.80 FL	*593.80 FL
5	1		*FRONT BUMPER	Dented	685.20 FL	*645.10 FL
6	1		*FRONT DOOR RH	Repair	1,772.70 FL	*- FL
7	1		*FRONT DOOR PILLAR RH	Repair	611.80 FL	*- FL
8	1		*FRONT DOOR RUBBER RH	Not Necessary	334.20 FL	*- FL
9	1		*FRONT DOOR LOCK RH	Not Necessary	407.70 FL	*- FL
10	1		*FRONT DOOR TOP HINGE LH	Not Necessary	85.60 FL	*- FL
11	1		*FRONT DOOR LOWER HINGE LH	Not Necessary	85.60 FL	*- FL
12	1		*FRONT DOOR CHECK LH	Not Necessary	72.70 FL	*- FL
13	1		*FRONT DOOR SIDE MIRROR RH	Damaged	470.20 FL	*188.20 FL
14	1		*FRONT DOOR INNER BOARD RH	Not Necessary	621.50 FL	*- FL
15	1		*FRONT WIPER PANEL SIDE GARNISH RH	Bird Droppings	212.70 FL	*212.70 FL
16	1		*FRONT STEP PANEL GARNISH RH	Not Necessary	123.40 FL	*- FL
17	1		*FRONT STEP PANEL RH	Repair	157.70 FL	*- FL
18	1		*FRONT RIM	Not Necessary	247.70 FL	*- FL
19	1		*FRONT SHOCK ABSORBER	Not Necessary	132.70 FL	*- FL
20	1		*FRONT TOP ARM	Not Necessary	345.50 FL	*- FL
21	1		*FRONT LOWER ARM	Not Necessary	407.60 FL	*- FL
22	1		*FRONT HUB BEARING	Not Necessary	122.70 FL	*- FL
23	1		*FRONT KNUCKLE ARM	Not Necessary	470.20 FL	*- FL
24	1		*FRONT STICKER RH	Necessary	15.00 FS	*15.00 FS
25	2		*FRONT TYRE	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)**9,150.40****2,629.00**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					2,233.85	653.50
Total Parts (S\$)					6,916.55	1,975.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	600.00
2	CHECK WIRING	New	80.00	20.00
3	RUST PROOFING	New	120.00	30.00
4	REMOVE & REPLACE DOOR ASSEMBLY	New	160.00	0.00
5	REMOVE & REPLACE FRONT UNDER CARRIAGE	New	320.00	0.00
6	ALIGNMENT	New	60.00	0.00
7	SPRAY PAINTING	New	1,000.00	880.00
Gross Labour Cost (S\$)			2,940.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >