

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21007057/KQCE2

Date: 17/08/2021

REFERENCE

Insured/Claimant:	Siong Hong Seafood Enterprise Pte Ltd	Policy No:	DMCVSNW00083762000	Claim No:	SNM21D202864/C01/TOHHS
Date of Loss:	15/05/2021	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD3406Z	Engine No:	1KD2414469
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y80K203208
Reg. Date:	09/09/2014 (Man. Year: 2014)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$38,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Yokohama 2/2 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Yokohama 2/2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,445.00	5,385.00	60.00	1.10
Miscellaneous Items	3,940.00	3,803.00	137.00	3.48
Labour	848.40	806.40	42.00	4.95
Paintwork Labour	1,079.75	1,079.75	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,313.15	11,074.15	239.00	2.11
Approved Total (Overridden) (S\$)		8,500.00		
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	11,313.15	8,000.00	3,313.15	29.29
+ GST 7.00/7.00% (S\$)	791.92	560.00	231.92	29.29
Nett Amount (S\$)	12,105.07	8,560.00	3,545.07	29.29

INSPECTION

Date of Assignment:	25/06/2021	Present Location:	S & H Motor Pte Ltd (Sin Ming)
Date Inspected:	28/06/2021	Inspected At:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	12.0 days		

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Aug 2021)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD3406Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Parts		5,065.00 F	*5,005.00 F
<u>Supplementary #1</u>						
2	1		*LH front seat belt	Jammed	380.00 F	*380.00 F
					Total Parts (\$\$)	5,445.00
						5,385.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Misc	3,940.00	3,803.00
Sub Total (\$\$)			3,940.00	3,803.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Labour for paintwork	New	1,079.75	1,079.75
<u>Labour Items</u>				
2	Labour for panel/mechanical	New	848.40	806.40
Gross Labour Cost (\$\$)			1,928.15	1,886.15

Report was unsubmitted during this print-out.

< END OF ESTIMATES >