



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV13858/CHONG KIA KEONG Reg No/Reg Date SMX9695E / 08/02/202 Date In/Mileage / 0 Chassis No KNAF5416MM5097459 Engine No G4FGKH741487 Make/Model KIA/CERATO 1.6 A GT LINE H370 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	26/06/2021/ 08:44	BLE	261 / Edwin Caina	35297		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER , RH FENDER , FRT SUPPORT & RH ROCKER SIDE SILL PNL REPAIR RH F DOOR , RH A PILLAR & BONNET				2 X 470			800 2400.00
E PNT98000 RESPRAY FRT BUMPER , BONNET , RH FENDER , RH A PILLAR , RH F DOOR & RH ROCKER PNL SIDE SILL				4 X 480 (CRS)			1920 2100.00
E PNT88000 REMOVE & REFIT AC COND & RADIATOR							? 100.00
M SUNDRY TOP UP AC GAS							? 80.00
M SUNDRY TO RENEW RH F SPORT RIM & TYRE							30.00
M SUNDRY SUPPLY RH F TYRE							? 380.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment							120.00
A 33900099 RENEW FRT U/CARRIAGE RH							400 800.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS							40.00
M SUNDRY SUPPLY BODY PNL SEALANT							X 80.00
M SUNDRY Sundries							20.00
M COVER-FR BUMPER				1.00	633.00	20.00	506.40
M GRILLE ASSY-RADIATOR				1.00	328.00	20.00	262.40
M GARNISH-RADIATOR GRILLE				1.00	38.00	20.00	30.40
M MOULDING-FRONT BUMPER,RH				1.00	216.00	20.00	172.80

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV13858/CHONG KIA KEONG Reg No/Reg Date SMX9695E / 08/02/202 Date In/Mileage / 0 Chassis No KNAF5416MM5097459 Engine No G4FGKH741487 Make/Model KIA/CERATO 1.6 A GT LINE H370 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	26/06/2021/ 08:44	BLE	261 / Edwin Caina	35297			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	LAMP ASSY-SIDE REPEATER, RH	CUT			1.00	143.00	20.00	114.40
M	AIR DUCT-FR BUMPER, RH	XAN			1.00	14.00	20.00	11.20
M	ABSORBER-FRONT BUMPER ENERGY	XAN			1.00	84.00	20.00	67.20
M	STIFFNER-FR BPR LWR	XAN			1.00	114.00	20.00	91.20
M	BRACKET-FR BUMPER UPR SIDE MTG	BR			1.00	22.00	20.00	17.60
M	ULTRASONIC SENSOR ASSY-P.A.S	XAN			1.00	163.00	20.00	130.40
M	LAMP ASSY-HEAD, RH	BR			1.00	2210.00	20.00	1768.00
M	PANEL-FENDER, RH	00			1.00	430.00	20.00	344.00
M	GUARD ASSY-FRONT WHEEL, RH	TN			1.00	95.00	20.00	76.00
M	MOULDING ASSY-SIDE SILL, RH	BR			1.00	279.00	20.00	223.20
M	ORNAMENT-KIA NO.115	REC			1.00	32.00	20.00	25.60
M	GEAR ASSY-STEERING	XAN			1.00	770.00	20.00	616.00
M	KNUCKLE-FRONT AXLE, RH	XAN			1.00	350.00	20.00	280.00
M	HUB ASSY-FR WHEEL	XAN			1.00	436.00	20.00	348.80
M	BAR ASSY-FR STABILIZER	XAN			1.00	238.00	20.00	190.40
M	LINK-STABILIZER	XAN			1.00	72.00	20.00	57.60
M	STRUT ASSY-FR, RH	XAN			1.00	280.00	20.00	224.00
M	BEARING-STRUT	XAN			1.00	86.00	20.00	68.80
M	BEAM COMPLETE-FR BUMPER	XAN			1.00	497.00	20.00	397.60
M	CARRIER ASSY-FRONT END MODULE	BR			1.00	675.00	20.00	540.00
M	CROSSMEMBER COMPL	BT			1.00	1156.00	20.00	924.80
M	ARM COMPLETE-FR LWR, RH	BT			1.00	286.00	20.00	228.80
M	STAY RH	XAN			1.00	22.00	20.00	17.60
M	WHEEL ASSY-ALUMINIUM	CUT (L RH)			1.00	926.00	20.00	740.80

Estimate

SURVEYOR NAME: Steve CLKK 28/6/21, 12.00pm

SURVEYOR SIGNATURE: OD-M AL

DATE: EX111-1

REMARKS: P/P, My Bel Sy

SURVEYOR NAME: Steve CLKK 28/6/21, 12:00pm
SURVEYOR SIGNATURE: OD-MAL
DATE: EX-111-1
REMARKS: P/P, My B/L sy

Confirm & accepted by hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

9 dys

7% GST on 14776.00

Nett 14,776.00

Total Payable 15,810.32

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.