

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG20014028/GTF3E2-1

**Date:** 16/07/2021

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29141713MKF
<b>Claimant Vehicle No :</b>	SJM3421L	<b>Insured Vehicle No :</b>	SLR4118G
Date of Loss:	15/12/2020	Nature of Claim:	TP
		Claim No:	632098

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJM3421L</b>	Engine No:	HR15068491B
Make & Model:	NISSAN LATIO, 1.5 AT ABS D/AIRBAG 2WD 4DR (A)	Chassis No:	JN1BAAC11Z0020848
Reg. Date:	29/12/2008 (Man. Year: 2008)	Odometer:	0 km
Colour:	Beige		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,454.16	3,493.61	3,960.55	53.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,672.50	1,665.00	1,007.50	37.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,126.66</b>	<b>5,158.61</b>	<b>4,968.05</b>	<b>49.06</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,100.00</b>		
<b>(S\$)</b>	10,126.66	4,100.00	6,026.66	59.51
<b>+ GST 7.00/7.00% (S\$)</b>	708.87	287.00	421.87	59.51
<b>Nett Amount (S\$)</b>	<b>10,835.53</b>	<b>4,387.00</b>	<b>6,448.53</b>	<b>59.51</b>

### INSPECTION

Date of Assignment:	17/12/2020	
Date Inspected:	17/12/2020 Inspected At:	Garage 13 Pte Ltd (HQ) 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46 Singapore 415875
Estimated Period of Repair:	6.0 days	

**Adjuster:** XING GUO QIANG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG    Version: 1.0 (Last Synchronised: 16 Jul 2021)

**Parts:** 143    NISSAN LATIO 1.5 AT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJM3421L)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Buckled	798.80 FN	*798.80 FN
2	1		*REAR BUMPER	Deformed	598.70 FN	*456.30 FN
3	1		*REAR BUMPER SPONGE	Compressed	35.60 FN	*35.60 FN
4	2		*REAR BUMPER BRACKET	Serviceable	91.80 FN	*- FN
5	2		*REAR BUMPER SIDE RETAINER	Necessary	70.40 FN	*50.00 FN
6	1		*REAR END PANEL	Bent	521.00 FN	*434.20 FN
7	1		*REAR FLOOR PANEL	Repair	985.20 FN	*- FN
8	1		*REAR FLOOR PANEL BOARD	Damaged	421.50 FN	*421.50 FN
9	1		*BOOT LID TOP LOCK	Jammed / Bent-in	121.50 FN	*121.50 FN
10	1		*BOOT LID LOWER LOCK	Serviceable	50.60 FN	*- FN
11	1		*BOOT LID WEATHER STRIP	Ripped	98.00 FN	*98.00 FN
12	1		*BOOT LID LOGO	Necessary	45.60 FN	*45.60 FN
13	1		*BOOT LID EMBLEM LATIO	Necessary	56.20 FN	*56.20 FN
14	1		*BOOT LID OUTER CHROME GARNISH	Bent	298.50 FN	*257.40 FN
15	2		*TAIL LAMP	O/S Cracked / N/S HolderBroken	498.80 FN	*498.80 FN
16	2		*TAIL LAMP PANEL	Repair	330.40 FN	*- FN
17	1		*REAR END PANEL TOP GARNISH	Deformed	99.00 FN	*99.00 FN
18	1		*REAR FENDER SPLASHIELD RH	Serviceable	35.40 FN	*- FN
19	1		*REAR EXHAUST PIPE	Repair	446.40 FN	*- FN
20	2		*REAR FENDER	Repair	1,709.00 FN	*- FN
21	2		*TAIL LAMP CLIPS	Necessary	9.00 FS	*9.00 FS
22	2		*REAR END PANEL TOP GARNISH CLIPS	Necessary	9.00 FS	*9.00 FS
23	1		*SET REAR REVERSE SENSOR	Malfunction	280.00 FS	*220.00 FS
24	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
25	1		*REAR END PANEL SEALANT	Necessary	40.00 FS	*40.00 FS
26	1		*BOOT LID KEYLESS SENSOR	Damaged / Malfunction	265.00 FS	*150.00 FS
27	1		*REAR BUMPER TOP STICKER (NECESSARY)	Not Consistent With The Impact	220.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,185.40</b>	<b>3,830.90</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (\$\$)</b>	731.24	337.29
<b>Total Parts (\$\$)</b>	<b>7,454.16</b>	<b>3,493.61</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	1,080.00	600.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL	New	1,200.00	800.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	100.00	60.00
4	TRANSFER OF EXISTING BOOT LID TO NEW BOOT LID AND REFIT THE SAME	New	45.00	45.00
5	CONDUCT WATER LEAK TEST FOR REAR PORTION ASSOCIATED REPAIR WORKS	New	45.00	0.00
6	REMOVE AND REBUILT REAR EXHAUST SYSTEM	New	90.00	90.00
7	REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING	New	76.50	40.00
8	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS ON ANGLE OF LIGHT INTENSITY)	New	36.00	30.00
<b>Gross Labour Cost (\$)</b>			<b>2,672.50</b>	<b>1,665.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >