

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21007064/KQF3E2

Date: 10/09/2021

REFERENCE

Insured/Claimant:	ONG KIM SUN	Policy No:	D21MCV0002275		
Date of Loss:	24/06/2021	Nature of Claim:	OD	Claim No:	MCV2021D0002754

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE8096X		
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Engine No:	1KD2591390
Reg. Date:	05/04/2016 (Man. Year: 2016)	Chassis No:	JTFAT35Y90K206148
Colour:	Silver	Odometer:	201772 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$52,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R12X8	Rear Tyre Size:	155 R12X8(D)
Front Left Side:	Michelin 7 mm	Rear Left Side:	Yokohama 8/8 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Yokohama 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,425.65	5,945.46	12,480.19	67.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,620.00	1,960.00	3,660.00	65.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,045.65	7,905.46	16,140.19	67.12
Approved Total (Overridden) (S\$)		6,300.00		
- Excess (S\$)	3,100.00	3,100.00	0.00	0.00
Nett Amount (S\$)	20,945.65	3,200.00	17,745.65	84.72

INSPECTION

Date of Assignment:	28/06/2021		
Date Inspected:	28/06/2021	Inspected At:	CT Auto Pte Ltd (HQ) 160 Sin Ming Drive, #02-14, Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Sep 2021)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE8096X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Serviceable	1,165.70 FL	*- FL
2	2		*FRONT WIPER ARM	Serviceable	236.20 FL	*- FL
3	1		*FRONT WIPER MOTOR	Serviceable	631.80 FL	*- FL
4	1		*FRONT WIPER PANEL	Repair	384.30 FL	*- FL
5	1		*FRONT PANEL	Bent	1,224.10 FL	*1,019.30 FL
6	1		*FRONT PANEL DYNA EMBLEM	Dented	79.20 FL	*65.10 FL
7	1		*FRONT PANEL INNER PANEL	Repair	597.40 FL	*- FL
8	2		*FRONT PANEL INNER PANEL BRACKET	Bent	267.80 FL	*267.80 FL
9	1		*FRONT AIRCON BLOWER	Cracked	1,272.40 FL	*1,218.00 FL
10	2		*FRONT AIRCON BLOWER HOSE	Serviceable	579.00 FL	*- FL
11	1		*FRONT AIRCON BLOWER AIR DUCT	Serviceable	241.30 FL	*- FL
12	1		*FRONT AIRCON COOLING COIL	Dented / Cracked	2,188.30 FL	*1,776.30 FL
13	1		*FRONT AIRCON COOLING COIL BRACKET	Repair	69.80 FL	*- FL
14	1		*FRONT DASHBOARD	Serviceable	988.80 FL	*- FL
15	1		*FRONT DASHBOARD CROSSMEMBER	Repair	743.80 FL	*- FL
16	1		*FRONT CABIN MOUNTING	Bent	1,224.90 FL	*1,056.20 FL
17	1		*FRONT STEERING BOX	Repair	3,962.40 FL	*- FL
18	1		*FRONT GRILLE	Cracked	613.20 FL	*481.00 FL
19	1		*FRONT GRILLE CENTRE LOGO	Necessary	80.20 FL	*56.10 FL
20	2		*FRONT CORNER PANEL	Repair	276.20 FL	*- FL
21	1		*FRONT HEAD LAMP	N/S Cut	1,922.00 FL	*852.10 FL
22	2		*FRONT HEAD LAMP LOWER RUBBER SEAL	Serviceable	96.60 FL	*- FL
23	1		*FRONT BUMPER	Bent	713.80 FL	*561.90 FL
24	1		*FRONT BUMPER REINFORCEMENT	Bent	486.70 FL	*216.88 FL
25	2		*FRONT BUMPER FOG LAMP GARNISH	No such part	236.20 FL	*- FL
26	1		*FRONT L/H DOOR	Repair	1,327.20 FL	*- FL
27	1		*FRONT WINDSCREEN MOULDING (\$224.90) (50%)	Necessary	168.68 FS	*112.45 FS
28	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
29	1		*FRONT WINDSCREEN SOLAR FILM	Not Necessary	450.00 FS	*- FS
30	1		*FRONT WINDSCREEN SUNSHADE	Not Necessary	350.00 FS	*- FS
31	1		*FRONT WINDSCREEN ERP STICKER	Not Necessary	50.00 FS	*- FS
32	1		*FRONT WINDSCREEN MOULDING SEALANT	Not Necessary	120.00 FS	*- FS
33	1		*FRONT WINDSCREEN MOULDING DAMPING SEAL	Not Necessary	120.00 FS	*- FS
34	1		*FRONT WIPER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
35	1		*FRONT PANEL SEALANT	Necessary	150.00 FS	*30.00 FS
36	1		*FRONT PANEL INNER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
37	1		*SET FRONT DASHBOARD CLIPS	Not Necessary	80.00 FS	*- FS
38	1		*SET FRONT GRILLE CLIPS	Necessary	80.00 FS	*80.00 FS
39	2		*SET FRONT CORNER PANEL CLIPS	Not Necessary	50.00 FS	*- FS
40	1		*SET FRONT NO. PLATE	Cut	80.00 FS	*20.00 FS
41	2		*SET FRONT HEAD LAMP CLIPS	Not Necessary	80.00 FS	*- FS
42	1		*FRONT L/H DOOR CO. STICKER	Necessary	150.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,827.98	7,838.13
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,402.33	1,892.67

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	18,425.65
						5,945.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT AND REPLACE FRONT DAMAGED PARTS	New	2,000.00	900.00
2	TO PUTTY AND SPRAY PAINTING FRONT PORTION	New	1,600.00	600.00
3	TO CHECK WIRING AND FOCUS FRONT HEAD LAMP	New	80.00	20.00
4	TO REMOVE AND INSTALL AIR CON SYSTEM TO FACILITATE THE REPAIR AND REFILL GAS	New	120.00	100.00
5	TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA	New	250.00	0.00
6	TO REMOVE AND INSTALL FRONT WINDSCREEN	New	120.00	60.00
7	TO REMOVE AND INSTALL INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	350.00	0.00
8	TO REMOVE AND INSTALL FRONT DASHBOARD	New	250.00	220.00
9	TO REMOVE AND INSTALL FRONT AIR CON BLOWER	New	250.00	60.00
10	TO REMOVE AND INSTALL STEERING BOX	New	450.00	0.00
11	TO PERFORM 4 WHEEL ALIGNMENT AND BALANCING	New	150.00	0.00
Gross Labour Cost (\$\$)			5,620.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >