

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 28 Jun 2021

Preliminary Advice

Vehicle No	: GBE8096X	Accident Date	: 24/06/2021
Make	: TOYOTA DYNA 150	Policy No.	: D21MCV0002275
Assignment Date	: 28/06/2021	Excess	: S\$0.00
Date of Inspection	: 28/06/2021	Est. Duration of Repair	: 6
Inspection At	: CT AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #02-14, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,045.65
Revised Amount	:S\$	4,986.10
Check Items (Estimated)	:S\$	5,403.13
Total	:S\$	10,389.23

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	52,000.00
COE / PARF Rebate	:S\$	11,484.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,516.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :