

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21007075/KRA3Q2**Date:** 19/08/2021REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 1900151579 |
| Claimant Vehicle No : | SMX8248U | Insured Vehicle No : | SKV1983K |
| Date of Loss: | 24/06/2021 | Nature of Claim: | TP |
| | | Claim No: | 8524373459SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No: | SMX8248U | | |
| Make & Model: | TOYOTA NOAH HYBRID, 1.8 X CVT (A) | Engine No: | 2ZR2H95211 |
| Reg. Date: | 29/01/2021 (Man. Year: 2020) | Chassis No: | ZWR800452231 |
| Colour: | Metallic Silver | Odometer: | 33543 km |
| Engine Capacity: | 1797 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 195/65 R15 | Rear Tyre Size: | 195/65 R15 |
| Front Left Side: | Goodyear 7 mm | Rear Left Side: | Goodyear 7 mm |
| Front Right Side: | Goodyear 7 mm | Rear Right Side: | Goodyear 7 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 5,588.50 | 2,490.75 | 3,097.75 | 55.43 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,400.00 | 1,380.00 | 1,020.00 | 42.50 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 7,988.50 | 3,870.75 | 4,117.75 | 51.55 |
| Approved Total (Overridden) (S\$) | | 3,100.00 | | |
| (S\$) | 7,988.50 | 3,100.00 | 4,888.50 | 61.19 |
| + GST 7.00/7.00% (S\$) | 559.20 | 217.00 | 342.20 | 61.19 |
| Nett Amount (S\$) | 8,547.70 | 3,317.00 | 5,230.70 | 61.19 |
| + Loss of Use (4.0 x S\$100.00/day) (S\$) | | 400.00 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| Nett Liability (S\$) | | 3,719.00 | | |

INSPECTION

| | | |
|-----------------------------|------------|--|
| Date of Assignment: | 28/06/2021 | |
| Date Inspected: | 28/06/2021 | Inspected At: Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143 |
| Estimated Period of Repair: | 4.0 days | |

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------------|-----------------|-------------|--------------|
| 1 | 1 | | *REAR TAILGATE | Bent | 1,812.00 FL | *1,712.00 FL |
| 2 | 1 | | *REAR TAILGATE HYBRID EMBLEM | Necessary | 50.00 FL | *50.00 FL |
| 3 | 1 | | *REAR TAILGATE INNER LOCK | Repair | 467.00 FL | *- FL |
| 4 | 1 | | *REAR TAILGATE INNER TRIM BOARD | Serviceable | 570.00 FL | *- FL |
| 5 | 1 | | *REAR TAILGATE RUBBER | Distorted / Cut | 372.00 FL | *372.00 FL |
| 6 | 1 | | *REAR WINDSCREEN MOULDING | Necessary | 120.00 FL | *120.00 FL |
| 7 | 1 | | *REAR BUMPER | Buckled | 545.00 FL | *545.00 FL |
| 8 | 1 | | *REAR BUMPER SIDE BRACKET LH | Serviceable | 74.00 FL | *- FL |
| 9 | 1 | | *REAR BUMPER SIDE BRACKET RH | Serviceable | 74.00 FL | *- FL |
| 10 | 1 | | *REAR BUMPER TOWING COVER | Serviceable | 25.00 FL | *- FL |
| 11 | 1 | | *REAR END PANEL | Repair | 435.00 FL | *- FL |
| 12 | 1 | | *REAR END PANEL UPPER COVERING | Mtg Distorted | 162.00 FL | *162.00 FL |
| 13 | 1 | | *REAR FLOOR PANEL | Repair | 698.00 FL | *- FL |
| 14 | 1 | | *REAR FLOOR PANEL TRAY BOX | Serviceable | 489.00 FL | *- FL |
| 15 | 1 | | *REAR FLOOR PANEL TRAY UPPER BOARD | Serviceable | 905.00 FL | *- FL |
| 16 | 1 | | *REAR TAILGATE INNER TRIM BOARD CLIPS | Not Necessary | 40.00 FS | *- FS |
| 17 | 1 | | *REAR WINDSCREEN SEALANT | Necessary | 80.00 FS | *40.00 FS |
| 18 | 1 | | *REAR BUMPER REVERSE SENSOR | Dented | 300.00 FS | *200.00 FS |
| 19 | 1 | | *REAR END PANEL UPPER COVERING CLIPS | Necessary | 30.00 FS | *30.00 FS |
| 20 | 1 | | *REAR END PANEL JOINT SEALANT | Not Necessary | 40.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (S\$) | 7,288.00 | 3,231.00 |
| - List Item Discount on L Items 25.00/25.00% (S\$) | 1,699.50 | 740.25 |
| Total Parts (S\$) | 5,588.50 | 2,490.75 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX & READJUST REAR ACCIDENT AREAS & ETC | New | 900.00 | 500.00 |
| 2 | LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR BUMPER ,REAR END PANEL ,REAR FLOOR PANEL & ETC | New | 900.00 | 600.00 |
| 3 | LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN MOULDING ,REAR WINDSCREEN SEALANT & ETC .TO EFFECT REPLACE OF REAR TAILGATE | New | 150.00 | 120.00 |
| 4 | LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC ,BACK TO ORIGINAL OPERATIONS | New | 120.00 | 60.00 |
| 5 | LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC | New | 100.00 | 50.00 |
| 6 | TO TUFF KOTE & UNDERSEAL MATERIALS | New | 150.00 | 30.00 |
| 7 | TO CHECK WIRING & CENTRAL LOCKING SYSTEM ETC | New | 80.00 | 20.00 |
| Gross Labour Cost (\$\$) | | | 2,400.00 | 1,380.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >