



CYCLE & CARRIAGE

AIG - OD CLAIM
SURVEY: 28/06/21
LKK - STEVE

VEHICLE NO : SJP 5420 K

MODEL : CIT/GCH 1.2 PURETECH

WIP : 16670

Material	:	\$	<u>4,787.20</u>
Labour	:	\$	<u>3,615.00</u>
Sub-Total	:	\$	<u>8,402.20</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>8,102.20</u>
GST 7%	:	\$	<u>567.15</u>
Grand Total	:	\$	<u>8,669.35</u>
Finalise By/Date : <u>LARRY ON 13/07/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 06 WORKING DAYS + 2 days (wk. end)

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1000	Cust No/Name /GOH CHYAN YEE Reg No/Reg Date SJP5420K / 27/12/2018 Date In/Mileage 10/07/2021/ 14287 Chassis/Package VF73AHNYTJJ793471 /# Engine No 10XTA41173070 Make/Model CIT/GRAND C4 SPACETOURE 1.2 PURETECH 13 Colour/Trim EBM LAZULI BLUE / 8LP TISSU MILAZZO G



Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
FAX00001	Credit	13/07/2021/ 10:59	BLC	884 / Lauro Songcuan	16670	0

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW BONNET, FRONT BUMPER, FRONT FENDER LH, REPAIR FRONT DOOR LH, FRONT AIRDAM				1250.00 ✓
E PNT88000 REMOVE & INSTALL FRONT AIRDAM				100.00 ✓
E PNT98000 SPRAY PAINT FOR FRONT AIRDAM, FRONT FENDER LH, FRONT BUMPER, BONNET, FRONT DOOR LH				1900.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				225.00 ✓
M SUNDRY APPLY SEALANT FOR AFFECTED PORTIONS				40.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
S SPECIALISTJOB SUPPLY ONE PC OF FRONT LICENSE PLATE WITH PLASTIC FRAME MODEL:CIT/GRAND C4				50.00 ✓
X EXC EXCESS FOR OWN DAMAGE CLAIM				-300.00
X FRONT BUMPER ✓	1.00	1031.00	20.00	824.80 ✓
X BUMPER BRACKET ?	1.00	330.00	20.00	264.00 ?
X BUMPER MOULDING ✓	1.00	207.00	20.00	165.60 ✓
X BUMPER MOULDING ✓	1.00	227.00	20.00	181.60 ✓
X BMPR RUBBR BOOT ✓	1.00	276.00	20.00	220.80 ✓
X CHEVRON EMBLEM SUPERIEUR ?	1.00	161.00	20.00	128.80 ?
X CHEVRON EMBLEM INFERIEUR ?	1.00	161.00	20.00	128.80 ?
X BRACKET SET ✓	1.00	125.00	20.00	100.00 ✓
X BRACKET SET LAT ✓	1.00	125.00	20.00	100.00 ✓
X PLUG LH ✓	1.00	96.00	20.00	76.80 ✓
X FRONT WING LH ASS ✓	1.00	571.00	20.00	456.80 ✓

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1000	Cust No/Name /GOH CHYAN YEE Reg No/Reg Date SJP5420K / 27/12/2018 Date In/Mileage 10/07/2021/ 14287 Chassis/Package VF73AHNYTJJ793471 /# Engine No 10XTA41173070 Make/Model CIT/GRAND C4 SPACETOURE 1.2 PURETECH 13 Colour/Trim EBM LAZULI BLUE / 8LP TISSU MILAZZO G

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
FAX00001	Credit	13/07/2021/ 10:59	BLC	884 / Lauro Songcuan	16670	0

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X ENGINE BONNET ASS ✓	1.00	1042.00	20.00	833.60 ✓
X FRONT LIGHT LH ✓	1.00	409.00	20.00	327.20 ✓
X HEADLIGHT ASSY LH ✓	1.00	718.00	20.00	574.40 ✓
X BUMPER BRACKET → Supp	1.00	194.00	20.00	155.20 X
X GUARD GRILLE INFERIEUR ?	1.00	311.00	20.00	248.80 ?
Z TEXT				
OD CLAIM - AIG				
DOA: 27/06/2021				
SURVEY: STEVE (LKK) 28/06/2021				
06 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	4,787.20	Nett	8,102.20
Labour	3,505.00	7% GST on	567.15
Standard Menu	0.00		
Specialist Job	50.00	Total Payable	8,669.35
Diagnostics Job	0.00	Paid	0.00
Sundry/Others	-240.00	Total Due	8,669.35
Total(w/o GST)	8,102.20		

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SJP 5420 K

<u>Materials</u>		<u>Cost \$</u>
1	Bumper Bracket (C16175368XT)	194.00 ✓ BR
	20% Discount	38.80
		<u>155.20</u>
	7% GST	10.86
	Total	<u>166.06</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE FRANCE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

Y
C

Y
C

CAR NO: SJP 5420KWIP: 16670 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	BUMPER BRACKET	? / SUPP		— RR	96 740 518 80
2	SET BUMPER LAT REINFORCEMENT EXT-BLANK PROXIMITY	? / SUPP	(LH)	— (W)	16 175 368 XT } Steve
3	STAKE GUARD CAPLLET	? / SUPP	(cond'n)	— RR	98 142 964 80 } 2/1/21
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: C4SURVEYOR: Steve

Reg No. SIP5A20K
Before using DIAGBOX to check all the sensors
got to be secured

User: DA11572
Vehicle: C4 PICASSO C4 SPACETOURER
VIN: VF73AHNYTJ793471

Print date: Friday, 9 July 2021 15:59:44

Start of vehicle session:

Tool version: 09.97



Home Documentation Measurements Reports

PROGRESS OF THE AUTOMATIC DETECTION OF THE VEHICLE

- ✓ VIN: VF73AHNYTJ793471
- ✓ Vehicle data retrieved
- ✓ Identification of the vehicle complete

CITROEN C4 PICASSO / C4 SPACETOURER (B78) ESTATE - LEISURE 1.2 i THP
130 (EB2DTS) AUTO GBOX 6-SPEED STT



Automatic detection of the vehicle complete

Script automatic vehicle detection s: 12.00



Global test

Expert/Global test

Vehicle\menu_tgref.s : 81_02

FAMILY NO.

CONTROL UNIT

11



Built-in systems interface

BSI2010_EV (11 Faults)

B181A 87

Fault in the response from the electric steering lock to the request for locking/unlocking

Properties

Cause

Local

Status

Intermittent

Features

No reply

B1808 87

Fault in the unlocking of the immobiliser by the engine management ECU

Properties

Cause

Local

Status

Intermittent

Features

Request missing

B1166 15

Front right direction indicator control fault

Properties

Cause

Local

Status

Intermittent

Features

Open circuit or short circuit to positive

B1167 15

Front left direction indicator control fault

Properties

User: DA11572

Vehicle : C4 PICASSO C4 SPACETOURER/C4

SPACETOURER (B78)

VIN: VF73AHNYTJJ793471

Reg No. STP 5A20K
After very spacer to Base all the sand
Job Done by
G.C

Print date : Friday, 9 July 2021 16:29:31

Start of vehicle session : 09/07/2021 - 16:00

Tool version : 09.97



Global test

Expert/Global test

Vehicle\menu_tgref.s : 81_02

FAMILY NO.

CONTROL UNIT

1



Built-in systems interface

BSI2010_EV (1 Faults)

B1003 00

Configuration fault (warning, this fault may be a phantom fault)

Properties

Cause

Local

Status

Intermittent

Features

-



Engine management ECU

VD46



Anti-lock Braking System (ABS) or
Electronic Stability Program (ESP)

ESP90



Automatic or piloted manual
gearbox

BVA_AM6_AT6_UDS



Controls under the steering wheel

★ ECU not recognised

Down-grade mode: this information is
not guaranteed



Controls on the steering wheel /
integral controls steering wheel

VCI



Left-hand windscreen wiper motor MOTEV_UDS



Right-hand windscreen wiper
motor

MOTED_UDS



Air conditioning

★ BCC

Important, ECU present on the vehicle
but configured absent



Driver's door module

PDPC_UDS



Automatic gearbox electric control
ECU

COMELEC2



Power steering

DAE_BVH2



Voltage maintaining device

★ **DMTR_DTC3B**

*Important, ECU present on the vehicle
but configured absent*

1



Motorised Boot Unit

VERINS_MOTORISES (1 Faults)

B1003 55

Configuration fault

Properties

Status

Permanent

Characterisation of the fault

Configuration incorrect or not carried out



Additional heating

Communication error



Hands full access ECU, right-hand
side or rear

BAAST



Touch screen

★ **EMF_DGT_LVDS_BD**

*Important, ECU present on the vehicle
but configured absent*



Electric steering lock

AVE



Urea ECU

Not present



Engine wiring housing

Not present



Trailer relay unit

Not present



External CD player

Not present