

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 2984C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR O/S (CONSISTENT)	TO REPAIR SEE LABOUR	1,792.20	-
1	FRONT DOOR HINGE O/S (CONSISTENT)	NOT NECESSARY	105.00	-
1	FRONT DOOR OUTER PILLAR O/S (CONSISTENT)	TO REPAIR SEE LABOUR	892.30	-
1	FRONT CORNER PANEL GARNISH O/S (CONSISTENT)	CUT	399.20	391.25
1	FRONT SIGNAL LAMP O/S (CONSISTENT)	BROKEN	250.10	201.29
1	FRONT SIDE LAMP O/S (CONSISTENT)	CRACKED	325.50	184.25
1	HEADLAMP O/S (CONSISTENT)	CRACKED	1,238.20	845.01
1	HEADLAMP LOWER RUBBER O/S (CONSISTENT)	TORN	38.00	38.00
1	FRONT GRILLE (CONSISTENT)	CRACKED	745.60	745.60
1	FRONT GRILLE LOGO (CONSISTENT)	NECESSARY	48.00	48.00
1	FRONT BUMPER (CONSISTENT)	BENT	1,422.20	1,033.21
1	FRONT BUMPER PAD O/S (CONSISTENT)	DISTORTED / TORN	455.10	381.20
1	FRONT STEP PANEL GARNISH O/S (CONSISTENT)	CRACKED	388.50	388.50
1	SET FRONT DOOR 'ROC' STICKER O/S (CONSISTENT)	NECESSARY	50.00	50.00
	LESS 50% DISCOUNT		-	-2,153.16
			8,149.90	2,153.15
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	30.00
	TO TRANSFER FRONT DOOR MECHANISM .	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING .	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR O/S AND FRONT DOOR OUTER PILLAR O/S .		750.00	520.00
	TO PUTTY & SPRAY PAINTING.		1,000.00	800.00
			2,000.00	1,350.00
	GRAND TOTAL		10,149.90	3,503.15

Report Ref No. CC4/ASM21007078/Ugs3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,500.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CC4/ASM21007078/Ugs3q2

CHUA KANG SENG

Licensed Appraiser